1/4 COR. 4-9 ORION 105-12 #520404

GOV. NOTES, OCT 6, 1853

WEST ON TRUE LINE BETWEEN SECTIONS 4+9
VAR 9° 48' East
39.98 SET 9R. SECTION POST
79.87 To SECTION CORNER

(520404) B

12-7-98
MW, EA

dug in fence line of dd posts dd wire & woven wire much filtered in soil on East side and plowed and washed away on west side dug 2' North & 3' South of line between Section Corners. from 1' west of Fence line to 5½' East of Fence line. Very poor soil Conditions Sandy s/t mixed up with gopher digging at all levels. We dug through 12" of Clay mix before hitting Clean Clay. Found Nothing. we dug 3' deep. Set CIC/5 Feldspar pipe on section line on East edge of N-S Fenceline Set post & spin 2' North of Corner