4-21-77 "Correction of corner" set C I M

~~9-23-68 set C/M over iron rod old soil pipe~~ (1)

1/4 corner 5-8 Orion 105-12 #320504

See Field Book 7 p. 99-101

6-1891 Chas Fraser P452 no 436 & 8 James Campion found stake reset by Hunter undisputed and B tree southwest - 74' ~~B tree pine 54" to~~ 60.

1/16 - south set stone M & L (no mens) To center (a ~~stone 5x6x20 set M & L this survey~~) at 1/16 cor No stone size given

Fieldbook 7 page 101 says set stone properly marked m & L between center and 60 link

8-1968 run & meas line from Center 8 north. found stone lying by large corner post answering size & above 1/16 stone at 1317.0 pushed line north (@5') met set pipe as corner.

9-23-68 set C/M in place of pipe (rec)

- corner lies 3' ± north of north edge traveled road running east & west. about 15' from center line.

No Good

disc on each side 6" brass corner post N 20.7.

1" x 24" split pipe up 2" under fence south 100.0

- fences running north and south on direct line.

4-21-77 Dug on the line from the S 1/4 Cor Sec 8 over the Center 8. Found a square mark in clay with wood piece (2' deep) Accepted this mark as the corner location. The corner came 5.13 W and 9.42' So of Kerr CIM (removed) Set a CIM over a 5/8" x 13" rod on the corner Corner came 4' N & 3 1/2' W of fence N & So. and 9.6 West of eye line of W. edge of 3 Harvestore silos N. of road

RP.s CSD S. side of pp # 44410 ENE 149.25
CSD N. side pp # 16542 ESE 152.52
Tree center + telephone box N25.1 (Corner .91W of calc. 1/4 line)

1/4 COR. 5-8 ORION 105-12 #520504 (2)

GOV. NOTES - Oct 6, 1853
WEST ON TRUE LINE BETWEEN SECTIONS 5 & 8
VAR 10° 32' E
39.91 SET POST 9R. SECTION CORNER D7
BR. OAK 8S 7E W 10S
BR. OAK 9N 6E W 11S

79.82 TO SECTION CORNER D3 1/4 8-9

Old Hunter fieldbook 5, Page 94 "1/4 post missing and witness tree gone. Set it midway between A and B."