1/4 CORNER 9-16 ORION 105-12 X April 1980 #520904

Set CI cap in pipe

GOV NOTES - Oct 6, 1853

WEST ON TRUE LINE BETWEEN SECTIONS 9 & 16

VAR 10° 8' E

40.05 SET 9A. SECTION post

BR. OAK 6S 76 W 476 = 314.16'

BR. OAK 15 N 81 E 181 = 119.46'

Both B.T.'s gone Apr. 1, 1982

80.10 TO SECTION CORNER

4-21-1980 Set C.I. cap in square pipe about 2' long. Set this 1/4 corner by mean. midway E-W and about 3' North of line between section corners. This location seemed to fit the E-W fence better than the midway and on like point which we considered. Dug hole about 5' dia. down to yellow soil but did not find anything. Also dug around brace post which is near corner location but set. This 1/4 corner

fits an average of line from NE 16 over 1/16 Cor. post west of NE 16 but not distance. Also fits average line from West, NW 16 over 1/16 corner East of NW 16 and distance is within 1.5' of the 1/16th post This location also fits line of fence at appx. 1/16 Cor North.

1/4 Cor Monu. is ± 1.5' So. of E-W fence and 9' West of fence to North (sign post 1.5' North)

Spike & CSD in 20" Bur Oak NE 22.15

Spike & CSD in 10" Bur Oak NE 41.50

Center of corner fence post ENE 9.2

Center of brace post NW 2.4

12-9-98

1/4 COR 9-16 105-12 ORION (520904) C
FOUND CIC/pk IN GOOD CONDITION WITH
SIGN & POST 1 1/2' NORTH.