X

#521005

section corner 9-10-15-16 Orion 105-12
5-1903 Armstrong P50B S 11-12-13-14 F Halloran.
J Juiske
Moore.

said corner to set NW cor 14 by prop meas.
Plat say 40.02 west and 39.81 east of NW 14 actually it proves 39.81 (2627.5) is correct. no desc of corner

---

7-13-62 J Kerr B85 P60 S15 Regstd.
new north line 15 found 1" pipe 1.0 north 4" iron pipe corner post. south hwy 52, west several hundred feet from County highway. 7.
— county also uses corner as described.
meas east to 1/4 C/M 2626.5 ±

1941 CHD (archie) B 127.P4. found old stake & stone
2' east of fence corner.
- ran - N-S section line. set 1/4 15-16 M&L 2622.4' ±

1891 T. Fraser old field book (7) pg 99-101
Found (Large) boulder with stake said to be
placed on original mound by Fisher
& others 2 miles west short 6' 10".

GOV. NOTES - OCT 6, 1853 WILLIAM JONES
80.00 chs. SET POST CORNER TO SECTION
NORTH BETWEEN 9-10-15-16
SECTIONS 15 & 16 - VAR 9° 35' E

BUR OAK	6 N	38½	W	171
"	6 S	26½	E	24L
WHITE "	8 S	14	W	228 -
" "	8 N	5	W	272

all B.T.s appear to be gone on Photo - 11-2-79 RuB

3-31-1980 Co. Surv. - visited Corner - fd 1" iron pipe on N. side of 5" dia. iron Cor. post and a wood Cor. post is ± 1½' N. of pipe ±2' dia. boulder is lying East of 1" pipe

30" Oak - 130' East (W. one-half of Twincorks)

12-9-98

✓SEC COR 9-10-15-16 105-12 ORION (521005) C
FOUND 1" PIPE IN GOOD CONDITION. CORNER FALLS
BETWEEN IRON C.P. + WOOD C.P. 1' S OF FENCE
LINE EAST & IN LINE OF FENCE NORTH.