/ 10-8-71 found stone #521106 (1)

6-10-74 set 3/4" pipe with reinforcing inside flush with surface of concrete

1/4 Corner 10 - 11 Orion 10 5 - 12

5-1877 Hunter P 311 No 305 Dll Hopkins

corner gone, road washed out no traces, but Mr Burke avers. he set fence running west exactly in line of original corner and corner past 2 rods from orig cor. set stone 4 x 5 x 24 at this point thus established.

1/16 corner south set stone 6 x 7 x 32 M&L 19.96 1317.36 N 1° W

1/16 center DW 1/4 11 set marked stake 19.92 M&L E-W 1/16 line.

10-1923 Co H D B 41 P 17.

hut in center road ??

over

Lp in fence post NE 53.8
Lp in Tele pole SE 75.1
Δ PI 0° 17' left from north
Mean north 2642.7

10-8-71. Co surv. dug with Rotman Cat for stone
- found 4x5x24 L stone set 5-1877. 6' deep.
- set limp rail over corner. mated after grading.
51.74 E to hard cone nail on S side large.
Create corner post of fences E-N-S.
115.43 NW to orange cap. directly over center
No plate # 1697. on E side pole.
lines fairly with E-W. ¼ line fences.
1.54' West ℄ Co. Road #7 3/4" pipe with rod in middle

1/4 COR. 10-11 ORION TWP #521106 (2)

OCT 6, 1853 GOV. NOTES

NORTH BETWEEN SECTIONS 10 + 11
VAR 10° 30' E
40.00 SET QR SECTION POST ASO
OR. OAK 8N 3E 1048

5-23-97 CHD FOUND PIPE IN GOOD CONDITION IN CONCRETE CR#7
DOWN 4" IN BLACKTOP. 1.8' W & E.

J(521106)

6-25-99
MW, RF, AE

1/4 Cor 10-11 105-12 ORION 55
found pipe 4" deep, 1.8' w of ℄ CR#7

Set 1" sq. pipe w/Cap NE of
Corner 36 1/2' East of ℄ CR#7
and 52' North of 1/4 line to east

TC@ Ref pipe
2Rt Pk in PP
of Corner on
to 1/4 Cor
West ℄ 1st pole South
side CR#7
10-11
Cant See low enough

To 1/4 Cor 10-11
VA 89°49'47" dh oz
Slope 64.715 Hor 64.715

2Rt Wright to 1/4 Cor 10-11
36°08'41" dh 00 38°22'11" dh 00
0°02'57" dh 01 2°16'28" dh 01
36°05'44" 36°05'43"

To WRIGHT
VA 91°30'24"
Slope 1885.17 Hor 1884.52