4-15-1966 set C/M over 3/4" x 12" iron rod close to rock. #521305 (#1)
completion of corner 10-21-76 CJM

section corner 13-14-23-24 Orion T05-12

5-1873 Hunter P277 no 274 L13 Rinderknecht etal

Field Book 4 P46-47

Corner missing, reset from 2 B trees standing & stump.

GOV'T B/T-S

Reset stone 2 x 7 x 24 from B trees

S B.oak 10" S12°W 200 lks
Red oak 8" S44½E 81
Blk oak 8" N82½W 89
Burr oak 9" N16°E 22

1/16 north set stone 2x7x28 M&L 20.03

-east 39.88 to stone set M&L. N88½°E

-also found corner - 1878 P336 no 330 no mens

4-1903 Armstrong P48B L23 Manette-Halloran.

Corner gone. set stone 2x17x24 by meas north to 1/16 20.04. - south 40.08. - east 39.83 - west 79.96

Came 4' west and 10' south corner past.

3-1904 Armstrong P74B L23 - Halloran

(over)

found stone placed P 48 D.

4-1966 J Kerr

road grading destroyed corner. reset corner 10' south and 4' west old fence. both fences have large trees in lines.

Center 24" burr oak (scars on S side) S. 61.5

" 15 " " 3' south fence line running ent. ENE 22.2

Placed C/M - came in east private road. ditch.

Note: C. Armstrong stone in place in 1975 - R.B.

remarked 10-76 [illegible] [illegible]

Section Corner 13-14-23-24 Orion 105-12 #2
#521305

1/16 N (9-28-76) Found ~~marked~~ stone of recorded dimension on N side of corner post to fences W and S. Post also W. post of gate. Monument and other corners found indicate this stone South and West of true corner location

10-19-76 Found mark in clay originally stood 8.11 N and 10.00 E of stone with bearing out post 1½' W.

---

10-7-76 Dug off E. half of N-S road from 7' N of C.A. stone (traverse pt) N to 5' N of fence E. digging from 5' W of stone to 16' W of stone. Found nothing

10-11-76 Dug along S. side of previous digging. Found nothing

10-21-76 Set CIM over ½" x 2' rod on E. edge of driveway at double the line and measure to ¼ Cor 13-24. This location f.t line from NW 13 over mark found at 1/16th N. Removed Kerr C.I.M which was 5.0' E and 4.0's. Also removed stone believed to be C.A.; (left hub driven down for future work)

R.P.'s Spike & CSD N. side 23" Burr Oak ENE 26.25

CSD NW side corner post NE 11.47

Corner 8' S. of fence E but in line with old fence ridge E. Corner 7' E & N-S. driveway

Section Corner 13-14-23-24 Orion 105-12 (3)
#521305

9-26-78 Found the CIM 2' deep but in good condition after the road regraded. Set a CIM over and up to road surface. Corner 5'E & N-S road. Old RP's gone.

Took RP's

Sp & CSD (up 6') on So side most westerly 13" Burr Oak in fence East ENE 143.96

M.H.D control monument "Post" SW 295.03
Mn/Dt

Put Survey Marker Sign by "Post"