#521406 (1)

9-15-67 set C I M over 3/4 x 12" rod.
9/2+/78 small limestones laid flat by side & beer can
1/4 corner 14-15 Orion 105-12
5-1903 Armstrong P50B L 11-12-13-14 F. Halloran elev
found stone 1' south corner past 39.92 = 2634.72 M & L ?
to the ni corner [illegible]

9-1941 J Kerr B26 P5
corner now in open field - stone gone - set 1" pipe down 1.0' M & L 2633.9

9-15-67 J Kerr
set C I M in place pipe on prospect of using corner for Haloran - Herman survey.
RPS set 1941 over.

C/M over 3/4" x 12" rod, small stones lying flat in clean clay by side + beer can. Monument 1' deep with 5/8" x 9" renfore rod rise in open pasture with transit set on + cut in south headwall Hwy 52 culvert about 6' from west edge.

set vernier at 49°48' on cupola barn in Valley
or - 78° on extreme SW corner.
top west headwall on Eyota road.
Then turn to 183°55' go 390.59' to corner.

Co. Rd #7 - Road Align. Nov. 1969
Computation of Road align. & Land ties gives Mens. of 2633.84 from 1/4 14-15 To Sec. Cor. North.

183 55
49 48
134° 07'

1/4 COR 14-15 ORION 105-12 #521406 (2)

GOV. NOTES Oct. 6, 1853
North between sections 14 + 15
VAR 10° 20' E
40.00 SET POST FOR QR. SECTION CORNER
MADE mound and dug trench. ETC.

9-6-78 Dug from a point 8' East of Kerr's CIM, East for 19' by 3½' N and 3½' So. Found nothing. The straight line between the section corners came 13' East of Kerr's CIM. (using Kerr's SW 14)

9-28-78 Set a CIM over a ½" x 20" iron midway and on line between the section corners. The corner is 16.12 E. and [redacted] N of Kerr's CIM (removed). The corner is in a pasture SW of the intersection of T.H. 52 and Co. Rd 7. Set Survey Marker Sign & Post on So Side.

This monument can also be found by occupying Olm 21-78 and turning an ∠ Left From Olm 22-78 ⟹ of 137° 05' 47" For 412.33.

RP's to Olm 21-78: A cap/Iron in inland on the N. side of Co. Rd. 7 and T.H. 52 intersection and 67.2 N & T.H. 52
CSD E side pp# 17042 SSW 5.55'
eSD E side light pole N 80.90
CSD S. side light pole ESE 62.70

RP's to Olm 22-78: Cap/Iron on East shoulder Co. Rd 7 25.85 E of ℄ and 41½ North of center of driveway East to Greenlee farm.
RP's: CSD in pp # 16949 (up 7') E 23.35

4-12-79 We moved this corner .41 So and .01W to correct a comp error made when the corner was set. The angle and distance shown above are correct

521406 (3)

1/4 CORNER 14-15 ORION 105-12

5-23-97 FOUND CIM IN GOOD CONDITION IN FIELD DOWN 1'.