10-16-78 CIC

#521504 (1)

1/4 corner 15-22 Orion 10 5-12

5-1893 Jr Fraser P506 no 476 L22 Ozark Fox, Hasty

corner gone, F.G Leske owns corner came under fence running E & W - ran section line short 28 lks on using 1/16 stake set by Hunter east as line it placed 1/4 corner 15 lks north of straight line but exactly under fence as Leske claimed.. On taking NE B.T. stamp N 25° E 64 lks. set temp stake ~~It came~~ midway.

39.86 -

1/16 east - found Hunters stake N & L 19.93 set new stake by side old stake

(over)

1/16 south set limestone 20.12½ N & L.

GOV. NOTES - OCT 6, 1853
WEST ON TRVE LINE BETWEEN SECT. 15 + 22
VAR 10° 1' E
39.92 SET QR. SECTION POST
RED OAK 6 S 11½ E 72
RED OAK 6 N 25 E 64
79.84 TO SECTION CORNER

8-21-78 Doubled line and measure from mark found at the Center 22 over a stone found at the 1/16th North. ~~(Point center Pt. corner 1/4 N = E=W fence)~~. Dug 1½ E, 1½ W, 2' N, + 3' So. by 1½' to clay. Found nothing.

10-16-78 Set a CIC/P2 at the above location. Put a survey makers sign ~~and post~~ on a piece of tobacco 1' So. in the E-W fence. Corner 7' West of fence So. and 10½' E. of lane fence South.
RP's: CSD in fence post SE 21.37
CSD in N side near post on E. side of huge C.p. E 8.24

1/4 Corner 15-22 Orion 105-12 (2)
#521504

1/16th East 9/11/78 Dug from a point M&L between the calc. 1/4 Cor 15-22 (calc @ double line and measure of mark found @ Center 22 over the stone @ 1/16th North) and the mark found 7.15 E. of Kerr's CIM @ NE 22 for 4' West, 3' North, 3' East, and 7' South. Found nothing.