1 .10-25-76 CIM #521605

section corner. 16-17-20-21 Orion 105-12.
6-1894 R Fraser P 546 no 506 d 19-20 sec d 1/4 20.
found corner post to be corner by BT Trees SW, NE & NW
placed 3 x 8 x 23 stone on north side cor post.
east section line 20 short To lke or 39.65 N1°W

6-1902. R Fraser P 710 no 624 d 17 Sidney Burnap.
found. stone p 546.
1/16 west set limestone 19.95 1/4 M & L. 13/6 85
Meas. North. 39.98 1/4 (2638.84' to stone Set M & L.

10-25-76 Found stone 3" x 8" x 12" under E-W fence (top of stone shattered and gone) approx 200' E of fence - junction to fence N-S-E. stone over hole with wood pieces chiseled

into bedrock. Set CIM over ½" x 8" rod at corner with stone on S. side and disc coulter between monument and stone.

R.P.'s Spike and CSD NE side of 10" Cedar SE 34.93

Spike and CSD NW side 10" Cedar NE 42.2

SECTION CORNER - 16-17-20-21 ORION 105-12
NORTH BETWEEN SECTIONS 20 + 21 -VAR 10° 5' E

GOV. NOTES - OCT 6, 1853. WILLIAM JONES

80.00 SET POST CORNER TO SECT 16-17-20-21
RED OAK 12 N 61 W 20
BURR " 15 N 31 E 63
" " 12 S 61 E 63
" " 13 S 44 W 4[illegible]6