1 5-15-1973 set C1M over part of orig stone. #521905 (1)

8-18-82 Cert 3-6-75 set C1M cor.

section corner. west 19-30 Orion 105-12.

east 24-25 Pl Grove 105-13.

9-1885 Hunter P401 no 391 d25 J Tait, J Baker J French, D Brown etal

corner missing completely no knowledge by settlers for over 20 years, corner lost.

Meas NW 25 to d¼ 19 120.11 7927.26 set corner E 80.00 S.W. ~~NE~~ 24

Meas NE 24 to dE 25 159.48 - set corner N 79.74 dE 24

set burr oak stake 2' long 1052.56 well below surface 5262.84 (midway)

Meas west 39.93 to ¼ cor stone 2635.38 then 2644.62

1/16 south set stone 3x6x22 M & L 19.93½ 1315.71

Meas east to ¼ 19-30 40.11 2647.26

9-1885 Hunter P403 no 392 d24 D Lowrie J French

found corner above P401

Gnes)

Meas west 39.93. To stone. 2635.38 - then 2644.62

Meas North 39.97. To assumed corner stake see 1/4 cor.

2638.0'

6-1894 W Fraser P 546 No 506 S 19-20 See S 1/4 20

corner gone dug 10' square 4' deep placed. Dug limestone set on reference mentioned P 401, 50 links west old road fence (running south east side of road) and 48 links north line old road fence running east on south side road.

did not meas. set 1/16 East, 1/64 was object

- East set stakes at 20.13 (1328.58 10.01 ± 10.01 (660.66

- North set stake N & L. 19.95 1316.7.

5-14 & 15 1973 Meas from north - dug on line main fence west and missed fnding corner. - dug again further south and easily found. most of large limestone set by Bill Fraser. set short C I M. over stone, much trash S 1/4 corner.

See Card #2.

#521905

(2)

Card # 2 West 19-30 Orion 105-12
East 24-25 Pleasant Grove 105-13

Meas N to W 1/4 19 Orion or E 1/4 Pl Grove 2631.4. R 2633.4
then N 2624.24 R 2623.5 to corner found W 18-19.

Meas E to stone found 1/4 19-30 2646.06. R 2649.9
which is on line and prop. distance.

Meas S. ± 5261 to MHD. corner in Hwy 30 also found one 1/16 stone 3/4 mile south no accurate meas to stone.

RP to C/M 44.3 SE to Conc Nail on E side Cor P for S & E.
31.25 W to point of angle of heavy angle Cor P.
85.9 ENE to 60 D in S side lone ash tree.

Gov. Notes 1853 Ball, Dep Sur.
North between 25 and 30
80.00 Set post and drove charred stake.

9-6-77 Took additional tie before road grading.
RP ½" rod and hub 2' So of fence West
W62.45

8-18-82, West 19-30: Dug down 3' to CIM in place. Set new CIM over it. Corner in ℄ N-S road and in ℄ road East, and 2' South of new fence West.

RP's:
- ½" rod 1' South of fence West West 62.92
  (old rod bent ⌊ removed)
- CSD in South side gate post WNW 31.53
- CSD in West side corner post NE 53.82
- Spike South side 24" Cherry tree ENE 85.81
- corner post SE gone and ⅄ iron C.P. West standing but bent.