/ Corner has computed coord. but no monument yet set. #522105 (1)

section corner 20-21-28-29 Orion 105-12.

reset stake on south Bank of brook from B tree which were all standing.

(3) 12-1875 Hunter P 288 no 284 S 28 A Burnap.

1/16 south set stake M & L. no meas.

---

(4) 6-1894 H Fraser P 546 no 506 S 19-20 see SW 20 coredit find corner but stumps of SE & SW BTs with marks plain and stump NW BT marks cut away. Meas of stumps agreed, bearings did not so set by meas only.

drove iron stake as corner.

1/16 west set stone 2X10X25 M & L. 19.93 1315.38

(over)

1/16 north planted stone M&L. 19.82 1/2. 1308.45
4 woodlot stakes set between 1/16 above & sec cor south

(5) 5-18-73. ran line from E1/M over stone at 19-20-29-30. east. set nail in line 1/16 fence several hundred feet north. and rather indefinate at 1318+' R. 1321.32
found ponted limestone as 1/4 20-29 at 2641.08 R 2642.64
- searched for 1/16 stone 2x10x25 east of 1/4 20-29
set POT east of 1/4 20-29 on slight depletion north.

as meas from S line 20 north varies.
from S W 20 N. R 2626.58 (Act very close)
from S 1/4 20 N R 2632.04. to orig 1856 corner.
from S E 20 N R. 2616.90 to 1844 M&L corner.
dug entire area with tractor for 1/16 in S edge road. 5' deep
all old dirt gone wash of floods full depth creek cuts in from N

Lo card # 2

#522105 (2)

Card # 2. 20-21-28-29 Orion 105-12.
Cont line last on random deflection plus 4' direct (5) N.
searched with magnetic detector entire area of SE 20
for iron rod set by 2d Fraser. Comes in flood area
where course of creek had changed several times.
No sign of anything or witness trees.
ran traverse north hoping to find recorded stone
set by 2d Fraser P 546 as 1/16 1308.45 (19.82½
found no stone in limited time spent. set 1"
basswood stake in edge woods just west of apparent
line up 20" ± at about 1306 ± from random.
point set up as 20-21-28-29. Stone should be
there unless deliberately removed. No shallow stone in area.

to reset 20-21-28-29, final, Center 20 should be proven or line continued east to try and find Will Fraser corner at 20-21 which may not be any where near ac center 20 date back to P16 9-1856 found with B tree and line Will used to set 1/16 between center and 1/4 20-21 ties up at 1894 M&L corner not orig govt corner which came in survey according to govt notes when witness corner set south. - long carefull search should be made for 2 Wills 1/16 stone; set M&L. 1308.45 the true key to both 1/4 20-21 and 20-21-28-29

10-28-76 Computed corner location from line from NW Cor 21 over 1/16th S. of 1/4 Cor 20-21 and at prorated W.F. measure. Dipped area for recorded iron. Found nothing.

SECTION CORNER - 20-21-28-29 ORION 105-12 (3)

North between sections 28 and 29 - VAR 11° 35' E #522105

(1)

Gov. Notes - Oct 6, 1853 WILLIAM JONES

80.00 chs SET post to CORNER AT SECT 20-21-28-29

ELm 9 S 14 W 69

MAPLE 10 S 34 E 48

ELm 12 N 27 E 36

BUR OAK 13 N 16½ W 56

(2)

July, 1856 Pg. 12 No. 19 Thos. Hunter Shows sec. Cor.

1/16 East 20.18 chs. m & L - B.T.'s (S 63¼° W 37 lks.) & (S 32¼° E 33 lks.

(52205)

7-2-99
MW AE

Sec Cor 20-21-28-29 105-15 Rock Dell
fd CIM 7" deep in Blacktop,
Broke head off after Cold Recycling
will set pipe 10' long

Prop Cor ——— North of 20-21-28-29
found 30d spike 60' west of ℄
CR #3 and in line of prop fence East.
Ref to 30d spike
Bottle Cap in Pt # 53005 WNW 42.00'
Punch Mark in Lug north end 18" CMP
NE 5.85