X · 10-6-1978 Set CI/cap over Sq. pipe #522405

section corner. 23-24-25-26 Orion 105-12.

5-1877 Hunter P 312 no 306 S 26. L. Schemerhorn.
corner gone. B T's gone, set temp point near corner of fence
where Mr Lorenzo Schemerhorn claimed corner once stood.
1/16 west set stake M & L. 19.95 1/2. S 89° 53' W. to
1/4 corner set from B Trees - not M & L.

4-1878 Hunter P 336 no 330 S 24-25 L Greenlee.
T Moore. stat.
took intersection fences east-north & south as aneed by Mr. Herrick
and L Schemerhorn. as having been built from true corners.
1/16 east set 1/16 stake marked 19.91 3/4 M & L

GOV. NOTES - OCT. 6-1853
80.00 CHS SET POST. CORNER TO SECT: 23-24-25-26
BR OAK 15' N 15 E 1310

10/6/1978 Steel fence post set by corner post in 1973 and old corner post now gone. Set a CIC/4'p² in line with the fence N-W-E.

RPs: CSD on NW side fence post with Survey Marker Sign WSW 1.92

CSD in N side of fence post ESE 2.00