1 6-20-1973 set C/M. over iron rod on results ①
Cor't 3-6-75 & electronic traverse. S.E. drawing on file
1/4 corner. 25-36 drion 10 5-12 #522504
4-1878 Hunter P 336 no 330 S 24-25 J Granlee.
found NE B T standing others gone. T Moore etal.
found stake remains & drove new marked stake in displace.
1/16 north drove marked stake M & L. 20.10 1/2. 1926.93

5-1886 Hunter P 405 no 394 S 36 L Wyllie M Morrisson
found marked stake, tested on B T stump. 1302.51
1/16 south set marked stake M & L 19.73 1/2 & witness stake
37 1/2 lks. east and 3" walnut S 45° E 21 lks. N 1 1/2° W.
1/16 center NE 1/4 36. marked stake M & L 19.98 1/2. on E-W 1/16 line.

4-1893 H Fraser P 505 no 475 SW 1/4 25 J Moore.
found 1/16 stake north P 336. drove new stake. on south bank river. (Gra)

6-20-1973 set RR spike at random by likely corner post under E-W-fence in line wood's fence running south. after electronic traverse computation set C/M over iron rod. at nearly same exact spot. found old post stub very near same place

19.74 W to 7 up cap in new gate post of fence west, new 6" Cmoted corner post.

25.2 due S to railroad spike driven very little into east side poplar tree

for meas & any computed distance see ~~field~~ Plat

1/4 CORNER 25-36 ORION 105-12 #522504 (2)

GOV. NOTES - OCT. 6, 1853
WEST ON TRUE LINE BETWEEN SECTIONS 25 AND 36
VAR 10°35' E
39.94 SET gr. SECTION POST
WHITE OAK 9S 13W 38
WHITE OAK 9N 9E 13
79.88 TO SECTION CORNER.

7/13/77 MNDOT FD CIM FLUSH WITH GROUND
TOOK RP's CONC NAIL IN DISC EAST 10" POPLAR 37.51'
CONC NAIL IN DISC SOUTH 20" POPLAR 25.29'
CONC NAIL IN DISC SE 12" POPLAR 58.23'
FENCES E-W-S