~~10/12/78 CIC~~ #522606 (1)

4/12/79 CIC

1/4 corner 26-27 Orion 10 5-12.

5-1877 Hunter P 312 no 306 2 Schemerhorn.

corner gone reset stake from B tree.

1/16 east set stake M & L 19.92 1/2 N 89°53'E

GOV. NOTES - Oct. 6, 1853

NORTH BETWEEN SECTIONS 26+27

VAR 10° 35' East

4.50 SLough 30 LKS WIDE LEVEL
RUNS S.E.

10.00 Enter Bl. OAK A15

35.00 Top of BLUFF. A100

40.00 SET QR. SECTION post
Br. OAK 12 N 26 E 9 dPO
BR. OAK 10 N 84 W 8
45.00 STREAM 20 LKS WIDE RUNS d30
S.E.

10/5/78 Dug from a point on line from the stake found @ the E. 1/4 Cor. 26 over the stone and stake found @ the 1/16th West and at Hunter's full measure from the E 1/4 Cor. 26 (We believe this point to be on far South and West [illegible] this corner could be) on following:



Did not find anything.

Calculated a Center 26 on line between the 1/16th E and the 1/16th W and at a prorated T. Hunter measure. Projected line from the E 1/4 26 over this calc. Center and doubled the measure from this calc Center over the 1/16th West and set a nail which came in line with the main line of the fence South.

1/4 Corner 26-27 Orion 105-12 (2)
#522606

10/12/78 Set a CIC/P² at the location of the nail set 10/5/78. Set a survey marker sign and post 1.3 North. The corner is 38' North of a ditch running WSW, and 68' NW of a large Elm used as the junction of fences South & Easterly, and in line with the fence South.

RP: 20" Hickory - Spike and CSD N. side NW 143.03
Sp. & CSD in N. side 18" Blazed Basswood Easterly 78.62

OVER

4-12-1979 We went to this corner to check two stumps found last year to see if the could be the stumps of the original bearing tree. The Northerly stump was 16" in diameter and the center had rotted out but on looking inside we found the old scar (we removed the photos with the scar to the office) We set a point at the bearing and distance recorded and the bearing and distance recorded to the Westerly stump coincided with Corp record. We dug about 2' square at this point but could find nothing. There was about 2' of soil and rock from falling up the hill that had slid down at this location. We dug through this before reaching natural ground. We removed the monument set last year and reset it 3.4 East at the bearing tree location. and set the survey marker sign on the north side. The center of the inlet is 45' South

RPs: Spike and CSD N. side 20" Hickory NW 145.1
Spike & CSD in N. Side 18" blazed Beechwood ESE 75.45