* 10/23/89 SET P² / C.I.C. IN PLACE OF #522806
STONE FD BY L.C.

1/4 corner 28-29 Orion 10 5-12 (1)

12-1875 Hunter P288 no 284. S28 A. Burnap
found orig stake standing tested B tree & stumps
corner stands 4 lks south of 8" forked white oak.
1/16 north set stake M & L and 4 woodlot stakes between

9-1879 Hunter P363 no 354 S29 H Buck.
found stake had been moved 3' west found hole where
stake was by B tree stumps. drove it well down mold hole.
still 4 lks south 8" forked white oak.
1/16 west set stake M & L 20.09

4-1901 H Fraser P2B S29 T Bernard, J Baker.
Fellows
(over)

found. remains old stake 4 lks south white oak stump
drove new stake with stone 1x9x14 by side.
1/16 west drove stake M & L 20.06.
then 3 stakes 5.01½ apart to Center 29. iron stake

10-27-76 Dug small hole on N. side of corner post and probed but found nothing. Did not search extensively. Mr. F.'s stake could be dug for especially if it comes S. of corner post.

GOV NOTES - OCT 6, 1853
NORTH BETWEEN SECTIONS 28 AND 29
VAR 11° 35' E
40.00 SET gr. SECTION post
45.00 ENTER dry timber bottom E + W d 150

#522806 (2)

1/4 Corner 28-29 ORION 105-12

July, 1856 Thos. Hunter Pg. 12 No. 19 Shows 1/4 Post.
1/16 East 19.86 chs. then 9.93 chs. to 1/64 cor then 9.93 chs. to Center Sec. B.T.'s to 1/16 Cor. (Blackoak 15" N 26¼° W 20 lks.)
(N 54 3/4° E 18 lks.)

10/23/89 LAND CONSULTANTS TD STONE (10/20/89) WE DUG OUT STONE 1x9x14 WHICH IS W. FRASER SIZE SET BESIDE STAKE. WE DUG DOWN BUT DUE TO ROOTS AND VERY DRY GROUND WE COULD FIND NO EVIDENCE OF STAKE. THERE WERE FENCE PIECES THAT LOOK LIKE A CORNER POST BRACE WIRE RUNNING OVER TO THIS AREA.
SET TELSPAR PIPE/C.I.C. AT STONE LOCATION, WITH STONE ON WEST SIDE

Cont →

Cont. Rp's
C.S.D. IN C.P. WEST 5.35'
C.S.D. ½ SPIKE IN 8" CHERRY SO. 5.28'
C.S.D. 'IN BRACE POST S.W. 10.13'
LINE OF FENCE SOUTH, WEST 5.5'
NAILED SIGN ON EAST SIDE OF C.P. TO FENCES E-W-S