X

#522809 (1)

1/4 corner Center 28 Orion 105-12.

(2) 4-1898 W Fraser P621 no 564 S28 S Oliver.
found stake set by Hunter P12 no 19.
set stakes south at 14.91 then 7.45½ more then 17.39½ to S¼28 N40W.
caption: In 1901 set stakes east 9.80 then 1961 more than 9.80 to E¼28 S89°W.

(3) 4-1900 ~~Robt~~ Fraser. P670 no 596 S28 J. White.
found stake P621. detailed woodlots.
1/6 west found stake location by Hunters B Lines 19.92½ ~~19.92½~~
6" W oak S 25° W 10½ lks – 6" W Oak N 26° E 16 lks.
1/64 west found old stake remains in ground.
9" S oak N 82½ W 23 lks – 6" S oak S 75½ E no mea.

J Kerr B-3 P 17 10-21-27

• found accpted corner.

(4) 10" elm. SSW 20.5
15" maple NW 26.6.

Visited This Center Sec. 25 — Oct 11, 1976 R.B.

(5) Corner area in springy mud slide, no corner post left line of fence East looks pretty good, No fence North except remains in Trees, fences South and West very crooked. Set lath in line of fence East and in line with Trees with wire in them going North. Kerr's N.W. B.T. could still be inplace (did not have info along Thisday).
— Set ½" x 2' iron approx 14' W. of lath to hold pt. in area of Center.

#522809 (2)

¼ Corner Center 28 Orion 105-12

(6) 10-13-76 - T. Hunter corner 9.79 ¼ E of Center 28 (BK 14 P. 17) Old Field Book
Found 1' sleigh runner referred to by John Kerr in BK 11 P. 17. Iron 1' S of E-W fence and in line of fence N.
R.P.'s 18" Black Walnut NNW 66'
18" Black Oak NW 46.3

– T.H. corner 8.75 ch. S of Center 28 (OH Field BK #14, P.17
Found stone found by John Kerr in BK. 11 P. 17.
Stone 2' S of fence E (fences N and E)
R.P.s Corner post ENE 7
Black Oak N 2E

July, 1856 Thos. Hunter Pg. 12 No. 19 Shows Cen Sec.
① with 4 B.T.s (N8¾°E 28 lks.)(N53¼°W 28 lks.)
(S 53¼W 33 lks.)(S 32¾°E 37 lks.)
1/64 North 9.98 chs. 4 times to 1/4 Post
1/16 Cor. north B.T.s (N 79¼°E)(S 25¼°E)
1/64 West 9.93 chs. then 9.93 chs. to 1/16 Cor. then 19.86 chs. to 1/4 Cor.
meas. South 39.78 chs. with a split at 8.75 chs.
1/64 East 9.86 chs. then 9.86 chs. to 1/16 Cor then 19.72 chs. to 1/4 Post.

For more information on Interior Breakdown- See
Microfilm Book A Pg. 12 No. 19

-Caption shows Remeasure in Feb. 1885.