/ SET ½" Sq PIPE 1 CAP 11-17-94 #522904 (1)

¼ corner 29-32 Orion 105-12.
9-1879 Hunter P 363 No 354 & 29 H Buck.
corner gone, dug extensively, B T's gone.
set stake well down N & L 39.91 2634.06
1/16 east drone stake well down N & L 19.95½ 1317.03
Bearings at corner N 88¾ E and N ½° W.

4-1901. W Fraser P 2 B & 29 T Bernard - J Baker
C Fellowe.
found iron stake N & L 39.94 in center road 2636.04
1/16 east set stake & stone 19.96 N & L 1317.36
1/16 north set stake & stone 3x6x21 N & L 19.95 1316.7
See Bk 5, Page 125

(over)

Gov. Notes - Oct. 6, 1853

WEST ON TRUE LINE BETWEEN SECTIONS 29 + 32

VAR 10° 33' E

39.93 SET gr. SECTION post

ASPEN 6 S ½ E 47

ASPEN 6 N 1½ E 353

79.86 TO SECTION CORNER

Sept., 1881 T. Hunter Old Field book #5 Pg. 125

¼ Post missing but measured from 1/16 Cor. East 19.95 ½ East of ¼ Post. set Temp. stake & Mr. Benham drove an Iron stake in its Place

6-1981 : ¼ Cn 29-32 : Dug, found nothing, cut.

6-17-1981, 1/16 Natl: Went to corner area, projected some fences and commenced a small dig.

1/4 CORNER 29-32 ORION 105-12 #522904 (2)

11-17-94 SET 1" SQ PIPE W/CAP IN TH #30 AT LINE + DOUBLE MEASURE FROM EAST FROM CIM @ STONE LOC AT NE 32 TO 1/16TH IRON OVER STONE. THE CORNER FALLS 5 1/2' SOUTH OF ℄ TH #30

℄ FARM DRIVEWAY SOUTH EAST 19'

C.S.D. IN PP # 49976 NNE 74.54