X 12-8-80 5/8" rod & cap #S23005 (1)

section corner West 30-31 Orion 105-12
East 25-36 Pl. Grove 105-13

9-1879 Hunter P 362 No 353 S 31 L Buck etal.

No corner could be found., center crossroads. so set temp stake as near center crossroads as possible as corner.
1/16 east set stone on line to N 1/4 31 at 20 chs from N 1/4 31
as near as mear for mile within a link of govt mear.
This made 19.87 from sec cor to 1/16 east. N 89° E.

9-1885 Hunter P 401 No 391 S 25 J Tait, J Baker, J French & Brown etal.
temp stake gone. rerun line from stone at N 1/4 31 over 1/16 cor stone west and placed stone 3 x 9 x 16 at recorded 19.87.

(over)

1/16 west set limestone M & L 19.93. 1315.38. to 1/4 stone.
1/16 north set " 2 x 7 x 22 M & L 19.93 1/2. 1315.71
1/16 center SE 1/4 25 at intersa lines. set stone.

Co Hwy Dept.
3" x 10" limestone, bridge apts on south side.
24" elm SE 66.43 — 20" boulder SW 46.8.

Gov. Notes 1853 Ball, Dep. Sur.
North between 31 and 36
80.00 Set post and drove charred stake

T.H. 30 R/w map 1955 - Stone inplace at Sec Cor.
PI 506+02.2 Δ = 0°15' LT from west (in center x-rds)
RP's 24" Elm - S.E. 66.43
P.P. - S.W. 66.52
Spruce NE 48.8

#523005

Section Corner West 30-31 Orion 105-12 (2)
East 25-36 Pleasant Grove 105-13

11/25/1980 East 25-36: Dug one bucket width (E-W) over 3/4"x10" iron found at surface of road. Found a 3/4"x24" iron down 18". Dug deeper and found several small irons. At 4.6' deep found 3"x9"x18"+ limestone standing with base in clay. Set irons around stone. Stone stand .13N and .33 W. of the location of the iron found at the road surface, Corner in center of roads N-S-E-W.

3/4"x24" iron c.n. N6.49 c.n. N6.28

3/4 x 10" iron c.m. N7.53 c.n. W6.41

stone c.n. 7.4 c.n. 6.0

RP's: CSD (up 5') in pp # 13345 SW 63.11
Spike and CSD (up 5') in 24" Maple SE 83.11
Spike and CSD in NW side of 14" Cedar NE 75.59
Mn/Dot CRP in 17" pine SE 99.88

12/8/80 (E. 25-36): Set 5/8" rod with cap over stone found 12/4/80 and set 3/4" iron .33 East and .13 South at M.H.D. P.I. location.

8-18-82, 1/16 North: Found fence West turn out and reference iron set 65.95 West (1977) bent over which way. Dug down to top of stone (down 22"). Found stone in good condition with steel fence post on North side. Top of stone 6½" x 2".
Set a 3/4" rod .05 East and .19 North of the center of the stone to be M&L between the SE Cr 25 and the E¼ Cr 25 (as set this survey).
RP's:- Punch hole top South end CMP in field drive West SW 27.67
- Punch hole top N. end CMP in field drive West NW 31.15