9-10-82 CIM

#523106 (1)

1/4 corner West 1/4 31 Orion 105-12
East 1/4 36 Pl Grove 105-13.

9-1879 Hunter P 362 No 353 § 31. H Buck etal.
no corner could be found or any knowledge except
settlers claim fence running east set from corner.
Set temp stake on line fence 2 rods west cor post
for setting center & 1/16 east.
1/16 east set stake prop dict - came 4 lks west 4" D. oak.
(1/4 corner should be set at least on straight temp line.
Why?)

Gov. Notes 1853 Ball, Dep. Sur.
North between 31 and 36
40.00 Set post and drove charred stake

7-1917 J. Kerr Field Bk -10 p. 27-29
page 29 indicates Kerr meas'd from E.1/4 post 31
To Something at this location called "Cor"
Dist 5276' (Note: E1/4 Cor. may have been his own M+L point.

5-29-81 N1/4 Cn 31: Dug with backhoe. Found nothing. Dug from 1' South of TN to 6' North & from 1' East of Trav. nail to 6' East. There was travel marks deep in the clay.

9-8-82, 1/16 East: Found nail shot in 1981 .7 North of the C.P. to fence N-S-E-W. Dug from post West for 9 1/2 by 1 1/2' North of fence (1' N. of nail) to 2' South of fence (2.7 of nail). Did not find anything. Line from E 1/4 Cn 31 would come over 2.6 South of the nail.

#523106 (L)

West 1/4 Cor. 31, Onion, 105-12
East 1/4 Cor. 36, Pleasant Grove, 105-13

9-10-82, W1/4 Cor. 31: Set a CIM over a 5/8" re-rod. at the intersection of the line from the NW Cr 31 to the SW Cr 31 and the line from the E 1/4 Cr 31 over the wood stake found at the Center 31. The corner is 2' E. & N-S road, appx 2' South of fence East and C.P. to Fence West (fence West now gone. Fin. line apparently set 1½' So. fence lines)
RP's:
Punch hole top N. end C.M.P. in field drain NE 50.40
Punch hole top S. end C.M.P. in field drain NE 25.53