#523404

S. 1/4 Corner Section 34 Orion 105-12
Gov. Notes 1853 Sept. and N See Cr 2-3 Jordan Twp.
West on south boundary of section 34
40.00 Set quarter section post.
Ash 10 in. N25W 20 lks.
White oak 20 in. N72E 84 lks.
40.24 White Oak 10 in. (or 20 in. ?)

8-16-1979 Dug from a point 3' North of the T.N. here, North for 17', West for 3', and East for 4'. There was 1' to 1½' of clay fill on clean clay. We found nothing. The road here may have been shifted South and the North road fence running West is 45' North of ¼

9-29-1979 Set a CIM over a 1" I.D. by 12" pipe in line with the fence North and by prorating Hunter measure from the iron found a ¼ Cor 2-3 over the property corner fence North of it. This position is 660.76' South of the 1/64th fence corner north and placed

the 1/16th corner East about .5 Nath and .5 West of the fence corner location. The corner is 14' North of & E-W road.

RP's:

Spike and CSD in NW side blazed 14" Maple NE 43.61

CSD West side corner post N29.76

At 1/4 Cn 2-3 Jordan Twp

8-14-1979 Found 1½" x 2½" topped iron on the North side of the corner pot to fence N-S-E