8-24-79 CIC #523406 (1)

1/4 corner 33-34 Orion 10 5-12.

2-1904 C. Armstrong P72B S 33-34 Sec 1/4 34-35.
B tree stumps not identifiable enough to set corner.
Run line set. 3" sq 24" oak stake M & L. 39.88
5" Joak. N 24° W 10 1/2 lks. tree marked.
11" " N 3°20'E 34 1/2 lks " "
Mean east 39.86 west 39.90.

---

1-1874 Hunter P238 No 24 NW 1/4 34 W Seymore.
found stake standing not orig govt. stake. found both
B trees - proved stake. 1 link off. reset correctly.
SEBT correct - NWBT is N 33° W instead of N 24° W
(over)

1/16 north – notched a 6" Jack Oak as this corner.
M & L 19.96.
set 6 stakes north of corner as woodlot corners.
N 3° W.
33 + 34
GOV. NOTES - OCT. 6, 1853
NORTH BETWEEN SECTIONS
VAR 10° 35' E
40.00 SET BR. SECTION POST d 20
WHITE OAK 16 S 76½ E 55 = 36.3'
" " 15 N 24 W 22 = 14.52
55.00 ENTER dry VALLEY N. E. S. W d 120
59.00 DRY BED OF CREEK 15 LKS WIDE RUNS N.E.
60.00 LEAVE dry VALLEY LEVEL A 40
67.00 Top of Ridge d 40
75.00 IN CAVING

1/4 Corner 33-34 Orion 105-12 (2)
#523406

8-17-1979 Dug 3' diameter on the West and North sides of the corner post. We found the stub of an old post on the NW side of the corner post. It was chisled way down into bedrock. Found nothing further.

8-29-1979 Dug from the corner post here South for 4' and East 7' by 2' to 3' deep. Most of the area appeared to have been previously dug or plowed since there was such a distinct line between the clay and the soil above it. There was appx 1' of soil washed in from the field SE and then appx 1' of more natural soil over clay. There was an 8" Elm 2' East of the corner

post so we could not dig there. We did not find anything. We set a CIC on a short piece of telepar on the corner 1.5 West of the traverse nail to be in line with the fence South and 8.36 South of the traverse nail to be on line from the E 1/4 Cor 34 over the stake found at the 1/16th West. The corner is 2' SSW of the corner post and 4 1/2 SW of the center of an 8" Elm.

RP's Center 3" Walnut SSE 15.7
Center 6" Walnut (up 5') SW 59.7