8-10-78 CIC

#523506 ①

1/4 corner 34-35 Orion 105-12.

2-1902 W Fraser P 30 B 35 Milligan, Bernard
Harder, Alson.

found stone set as corner with stake by side.
Elm BT. S 76° W 33 lks marks plain
corner lies 56 lks west of line & section corners
Meas south 15 lks shorter than north
1/16 north - drone slough shoe. M & L. 19.96½.
1/16 south drone stake M & L 19.89.
1/16 east drone iron stake 1½" dia M & L. 20.27.
N 89½ E

2-1904 Carmstrong P 72 B 33-34. for
Aber - Stengs - Scott - Underlook - Halloran - Murphy - (ones) Ferguson - L.O. Sanderson,

found stone by fence corner an B tree (elm).
ran to this corner from center sec 33. hard to follow work.

GOV. NOTES - Oct. 6, 1853
North between sections 34 + 35
VAR 11° 25' E
40.00 SET gr. section post
ELM 12 S 8 W S8
HACKBERRY 8 S 73 E 50
65.70 Enter CREEK 30 LKS WIDE, RUNS EAST
66.80 LEAVE CREEK, COMES FROM N.E.

See Old Field Book 5 Page 33.

8-3-78 Found a 3/4" x 2" x ? iron on the South side of a 4" x 8" x 15" limestone 16" deep in the ¢ of the old N-S road and 19' West of the fence on the East side of the road.

¼ Corner 34-35 Orion 105-12

#523506

8-10-78 Corner comes @ the North end of an old stone and concrete bridge so did not dig. Set a CIC on a 2' square pipe at the intersection of the line from the 1/16th E. of Center 35 (found) over the Center 35 (found) and the line from the NW Cor 35 (found) over the 1/16th South (found)

The corner is 2½' West of ℄ N-S road and 15½' South of a fence West and at the North end of bridge.

RP's: CSD in N. side pp # 16899 SW 45.21

CSD in E side e.p. NNW 17.73

Spike + CSD in SE side 29" Hackberry (with old blaze pointed facing corner) NE 40.67

11-4-1983, 1/4 Cor 34-35: The CIC/p² at this corner had been hit by the road grader but the bottom 18" of pipe was still undisturbed so took reference to that.

Set a 1"sq x 30" pipe 135.13 } this pipe 42' South of a 36" CMP
South and on line to a
1" sq x 30" pipe 323.41 South } this pipe 17' East of pp 45241

This corner must be replaced when new culvert put in.

(523506)

(44)

6-15-99
MW RF AE

1/4 Cor 34-35 105-12 ORION
Found 1" sq. pipe. Set (1983) on Transit line South. 135.13' South of Corner. pipe was slightly bent on top. Straightened pipe and drove back in existing hole
Found 1" sq. pipe @ 323.41 South of Corner Set on Transit line in (1983) in good Condition
Note: CIC/P² gone in Road Constr. & Culvert placement
T= 60°
P= 29.5
TC Pipe 135.13' So. of Cor
To Pipe 323.41' So of Cor
VA 90°12'34"
Slope 188.275 Hor 188.27
1983 dist = 188.28
Set 16" CIM over 5/8"x18" rerod from Ref Tie line from South The Corner falls 3' West of & driveway & 12' South of short fence West, and North of large diameter Concrete Culver running NE-SW
Spike in large Hackberry NE (1983) 40.67
NE (1999) 40.62

1.24 So.
1.04 W