X VOID #530106 (1)

¼ corner 1-2 Plea Grove 105-13.
7-1876 Hunter P301 No 296 L 1 N Real.
Corner gone, B trees gone, road graded "down" several feet took line of fence running west claimed to be set from orig corner as line to set center section 1.
See J. Fraser Survey P. 365 BK A.

6-1903 Armstrong P63P L1 Thos Donaldson.
evidently found or set no corner. according to plat, used corner past of fence running east as pilot to set line north.

8-1940 J Kerr B20 P62-65 L2-3-9-10. used 2" steel set by Co. wrong cor.
set 1" x 3' pipe on line betw section corners — Meas south 2619.62 — Meas North 2591.21 (over) 1938
There is chance this pipe set from orig stone N 1-2 not common cor

- Meas west to center 2 ~~2634.92~~ 2640.58

o
o o o in north end culvert. NW 44.42

" " south " " W ~~31.24~~ 1968(34.4)

N.-1968

set ½" rod 100' east on E-W ¼ line of section 2

RP this rod 41.5 to fence west -11.85 to fence north 28.85 to center base small 6" boulder N.W.

1/16 west set rod on random north of tele pole. to told line. tele pole-south-26.6. - Center field drive south - each 35± rod lies 5' ± south center road E & W about 4' from ledge

- Meas west to center 2 2640.2.

1/16 north set rod on section line at 1280.96 then 1309.10 rod is 130.6' NNW to pine tree leg on PP 16306 with 3 small transformers on it in center road

#530106 (2)

Card # 2 1/4 corner 1-2 Pleasant Grove 10 S-13 E

6-20-69 J Kerr reset corner with 1/2" rod until road has all its rock lifts. - found rod 100' east everything else gone. reset on line rod set at 1/16 are west.

set new ties

punched ~~[illegible]~~ single punch on top clamp holding

— place end of culv in place. south end 18" road culv under road running west (township road) SW 50.16.

— same on north end NW 57.75

— head of big nail (60D) driven clear in on east side power pole 163/0 up 18" NW 83.53

-over

-16 north found rod placed 7-1968 as 1/16 corner.
proved only way to set section corner north. Note- this rod
adjusted proportions as follows. true govt 1/16 corner but
1/4 1-2 North 1309.24 to 1/16 rod. all deeds call for N 1/2 1 being
1/16 rod north to section corner 1281.06. half & half or 1/16 point at
1295.15' see below.
RP 1/16 rod.
— punch mark in top calv end clamp very near east 37.87.
— pine tree symbol disc on PP# 16306. (moved in grading)
with 3 small transformers on. N N W 136.95
1/64 rod at 647.6 south of NW cor 1 in center road
RP 90.08 N N E to seam in E end conc calv apron
prop cor 50' E RP 86.05 to seam joint



Pleasant Grove 1/4 corner 1-2 Card (3)
#530106

Govt notes on back side

Good Notes M.G. Kerrick 1854 North Random 1+2

40.00 Sta A temp. 1/4 Stat.

East on true line between Station 1+2

39.57 Sta Stat. post

Bur Oak 8 in 50 W 91 lks

Bur Oak 12 in N 65 E 182 lks