#530304 (1)

X

¼ corner 3-10 P Mac Grone 105-13
9-1884 Hunter P392 no 383 & 3 & Pierson
found stone and stake in place, B Tree gone could not
test corner, accepted and left as is. no mear

6-1917 J Kerr P266B & 10 & Haney etal.
Field book -10 p. 13-15 — also Kerr BK 20 pg 2 —
found 4x8x18 stone in edge dry run.
- mear west 2640.1 to set col stone.
B Tree - 10" Oak N 44° W - 5.4'
8" Oak N 70° 30 E 20.1

1-1894 & Fraser. P542 no 503 & 4 L Nichols.
found stone set stakes every 10.01 west to see stone found. over)

19.65 J Karr. no books for setting corner. run line N 1/4 3 south. found at S 1/4 3. a deep wash some 6' deep and 8' wide at location recorded stone. Rea cut all trees - stumps resembling NW BT 1917 still in place. gully took NE tree. assumed spot of corner set 1/2" rod on true line (ran on 5' B act) on rise some 300' + - North with in 1.5' of large transmission power pole under line some 1.5' northwesterly of pole. no mear from N section corner stone west completely gone also.

9-29-71. found Ch Armstrong 1/16 east of S 1/4 4-9. placing 3-4-9-10 7 1/2 further west than set. 8-1968. Making mear from Thacker Cylinder iron set as 1/16 1320.8 from new S 4-9-10. rag on fence as 1/4 3-10 1316.7 west to iron. - believe now. A exact line (not eyeball proj from rod by Pob & Euler 3 south corner stood more.

#530304 (2)

Card # 2 1/4 3-10 Pleasant Grove 105-13
Cont 9-29-71. attemp to prone 3-4-9-10 are not
properly placed by JKell. 1969.
Corner set. on line from record limestones at 1/4 4-9.
and rod set conveintly as 1/16 on line fence south and
east at 1324.0 to 1322.7 allowing 1.3 for more
accural measure. When true 1/16 found 4.4 west and .8 north
knew corner set wrongly - would go 1.6 N and 7.5 west ±
- to help prone went to 1/4 3-10 to meas west. found
awful mess. Women mires with rag on bottom as corner
washed into gully with massive brush. tried to
reconstruct rag on fence estimated 00 as about 24.2 east
of center 8" elm stump on fence remains west. over

to really reconstruct 00 would have to return aerial from Center 3. over iron set north by Trans power pole. (1.5 ± NW pole) Neither J Kerr. 6-1917 or. 2nd Fraser 1894. claim Thrasher cylinder bar at 1/16 as corner. line run would prove it. No argument on N-S of 3-4-9-10 only E-W. which could be proven by finding stone on 25 acre line project S line 25 acre line to road & intersect line from 1/4 3-4 and corner as set at 3-4-9-10 dug. Twice by crops too tall. Very little gained now by finding 25 acre stone 825' S of 1/4 3-4 as lines now set up. Requires such massive digging.

2-76 Set 1/2" x 4' pipe up 3' in wash at double the line and measure of computed location See. Cr 3-4-9-10 on Thrasher cylinder at 1/16 East. ~~Cor~~ Pipe in line of fence South and 2' S. Fence West.

Note: Pipe location requires slight correction before final corner is set

Pleasant Grove 1/4 corner 3-10 #530304 (3)

Lot Values on Back

Since 3-4-9-10 Finalized, pipe in correct location @ 1/4 3-10

Cor'l Notes M.G. KARRICK 1854 ERS/ Random 3+10
40.00 Std Temp 1/4 Std. post
West on true line between Std 3+10
40.00 Std 1/4 Std. post 9°57'
Bur Oak 8 N 35 E 77
" " 15 S 52 E 153