Note Card #3 — Card 1 — 3-12-75 — (1)

7-28-1964 set C/M over 1" x 12" pipe.
3-13-1973 found true recorded stone - reset C/M over stone
section corner 5-6-7-8 Plane Grove 105-13 #530505
7-1856 Hunter P 13 no 21 L 5 J Brown, J Hartenbower.
used corner and set
1/16 east M & L 20.11.

9-1891 Thos Fraser P 458 no 442 L 5, N+S W Railroad.
Corner lost in graded railroad. Object to reset corner.
reset it by Railroad notes 23' west of station 3164+65
checked by 1/16 stone east 20.10 3/4 and stone 20.08 1/2 west.
1327.09 1325.61
Working south to check by
set stone 20 x 6/14 x 5

9 -1964 J Kerr to preserve corner.

found pipe in stones.

set C/M over 1" x 12" pipe.

RPs heavy rubber railway car hose coupling up 14" E 0.8'

Notch in SE corner conc whistle post WSW 43.55.

inside of north rail 90° angle from rails ESE 10.7.

20 D south side tel pole. NW 39.1.

Lead 120 D north side large willow W 92.0.

5-10-1958 J Kerr. B 93 P 576.

boulder with 3/4" pipe on S side RP whistle stop post SW 43.55

-16 N set ~~3/4" rod~~ 1/2" rod in blacktop ~~Old = 4-24-1976~~ M&L. ~~1315.83~~. ~~1317.64~~

SP PP NE ~~109.4~~ - Sp TP SE ~~70.8~~ set to old fence post at 4.5-6. not stone.

Card # 2 5-6-7-8 Pleasant Grove 10513 (2)
3-13-73 found stone in open field found by L. DeVal. #530505
at 1/4 6-7 and positive 1/16 stone east. set by
W Fraser. M & L. No mens given by Will just shot
measure of 20.08 1/2 (1325.61) 1/16 = pointed stone up 4".
in N-S fence just west of corner post.
- decided C/M set by JKerr 1964 too far east and north.
- found exact described boulder down 16" in ditch
5' south 9' west ± from C/M -
removed C/M (left pipe below) and placed C/M over
stone with rubber base on S side flush with surface.
with piece of railroad iron etc by corner. C/M in
Mound set rather high direct on boulder top over

RPS to corner.

37.5 SWly to SE corner Conc. whscb stop post.

old RP 43.55.

10.72 SEly to inside of north rail at 90° from rail

old RP 10.7

33.55 NWly to head of 20 D nail on SW side old tele pole.

old RP 39.1

44.45± 2' E & N to center old post may have been tele pole. aerial line west now near exact one 1/16 stone, random due to fact all corner could not be seen positive.

Chas Armstrong 5-1917. Book K P19.

stone at 1/16 west at 20.04. 1322.64. on plat.

1/16 Cor. N. - reset M+L 1317.64 elec. (4-20-1976)

removed old 1/2" rod which was 2.8' N. & 3.8' E. of our point

#530505 (3)

Section Corner 5-6-7-8 Pleasant Grove 105-13

1/16th Note: 4-11-78 Took references before road resurfaced. The corner is an iron 3' South of ℄ E-W road.
RP's: Chisel mark in top S. end of large concrete culvert WSW 178.40
CSD in the SW side pip # 43786 NW 92.00

Govt notes on back

4-16-1981 Co. Surveyor. - RR bed being leveled To the east of this Corner puts corner mons. in danger of being destroyed. I talked To dozer operator and he said he would work around the mons. location if I marked it.
~~Placed a Sign post and Swing marker sign ± 1' sw/o of mons.~~ Sign post removed
Took new Tie: C.S.D. in RR Tie Cor fence post - East - 113.1'
Line of Fence East of above Ties lines ± 4' North of mons.
other ties will probably be destroyed. RWB

Govt Notes M.G. Kamrath 1951

80.00 Std post, in Mound with triangle pins (hard) stakes + Oscar Orange Str. 6 at Each Bnd/z for Corner.

Str. Lots 5, 6, 7-8

10/17/62 CHD fd limestone

Rp's T.P. NW 34.0'

Conc. marker post SW 37.0'