#530804 (1)

/

1/4 Corner 8-17 Pleas Grove 105-13.

5-1856 Hunter P4 no 7 S 17.

Corner used to sub-divide section - line south.

1/16 south 19.86 N & L to center 17 for line east

5-1856 Hunter P5 no 8 S 8-9-16-17 bordering 1/4 s

Corner used. To sub-divide line south.

1/16 south - 19.86 N & L line east.

Bearings of lines at 1/16. N 1/2° E — S 89°10' E

1/16th North 19.85 M&L

4-1973 Dug with air hammer at this corner
— found nothing —

7-2-1975
Stopped at corner & found nail still in place.
Took R.P.'s

C.S. disc on S.W. side of yard Power Pole N.W. 73.05
C. Hwy dept disc on N. side P.P.# 9715 S.W. 56.42
Corner falls 9' South of ℄ of Road west
℄ in ℄ of N.-S. Bit. surface C.R. # 1

7-26-77 Set @ CIM over a ½"x 2' rod at the location of nail set in 1973 (?). Comer 1'E ℄ N-S road and 22' So of ℄ of road East.
RP's CSO SW side of yard power pole NW 73.00
Co. Hwy Dept Disc on N side of PP # 9715 SW 56.37

Pleasant Grove 1/4 corner 8-17 #530804 (2)

Cut Notch on Back

Gail Watts M.G. Karrick 1854 EAST Ramkum
8417

40.00 std A temp 1/4 std post

West true line std 8417 V 9° E

40.09 std 1/4 std. post in Mound with
trench pits & charcoal stakes on
Osage Orange std's NE - SW