12-13-1973 set ½" x 2' rod by line and meas. ①
2-2-1981 - Doug Knutson & J. Schwarz report that ½" rod has been plowed out - they reset a long spike from R.P.'s #531406

¼ Corner 14-15 Pleas Grove 105-13.

1-1894 St Fraser P543 No 504 & 15, John Clark estate.

Could not find corner. set white oak stake from properly marked SW BT still standing. Came in center rd road.

- Meas north 9.93¾ to white oak stake then
655.87 655.87
9.93¼ to ¼16 cor. an iron stake then
19.87½ to section corner. stake & stone found. S 1/4° E.
1311.75 659.0
- Meas west 9.98½ to stake then 9.98½ to ¼16 stake
659.0 329.5
then 9.98½ to stake then 4.99¼ to stake then
329.5
4.99¼ to center section. a 2 x 8 x 24 stone set this survey.

over)

– meas south 9.94 to stake, then 9.94 to 1/16 stake
656.04
then 9.94 to stake then 9.94 to sec. cor.
a 2 x 12 x 26 stone 1' east old cor post

5-18-72 Co Surv. Meas & ran line from C1M at
10-11-14-15 set small bolt at 1311.75 – cont S to 2611.75
searched at 2623.5 found some charcoal.
2-13-73 1/16 N found small bolt at point .86 east (nail) and found it to be
1312.21 – reset 1/16 with 60D nail .86 E .46 N of bolt
still subject to meas under more favorable conditions.
– set 1/2" x 2' rod on chainline at 2623.5 and 2636.04
from center 15. Moving point from north, west .07'
making 1/16 nail off a little which will be properly reset.

Lee Card # 2.

#531406

Card # 2 1/4 14-15 Pleasant Grove. 105-13 (2)
offset 35' south at nail at 1/4 2623.5 and at
center 15 stone and projected line west on this
line cutting all trees the bothered line. (some 8" dia
this line fell. 21.15' south of rod set as 1/4 15-16
4-17-72. which was set on line from wood lot corner
673.22 R 671.55 North too 1/16 stone
- final 1/4 15-16 about 646.8 south of woodlot corner R 645.15
- if line from east holds as true line ran by W Fraser in
1-1894. something is sure wrong with 1/4 15-16 as
set and at least 2 of 3 stones found north of it. a problem

(over

2-14-73. 1/4 14-15 - found traverse point by Nicklay driveway.
2' N & fence E - on line mailbox post and east edge road south.
also position RPs in traverse data.
re shot angles and distances from this point to Center 15 (center witness rod)
and 1/2" rod reset as 1/4 14-15.
re-shot line north directly to 10-11-14-15 found 60 D nail at 1/16 cor
exactly on - reset nail with 1/2" x 2' rod and referenced RP 1/16 North.
54.10 W S W to bottle cap and old disc on N Side PP ± 13190.
26.95 due E to long cone nail thru bottle cap on top of large
oak corner post of new fence running east
final on this 1/16 N & L 1311.75 as recalled by W.F. elec meas.
reset 1/4 14-15 with 1/2" x 2' rod. at 2623.5
no reference poles or trees. Corner 3.66 E of lower wire of
woven wire and 5.25 SE of steel corner post - rag on fence.

2-2-1981 Dave Knutson + Jerry Schwarz report that 1/2" rod
is plowed out they reset long spike from Ties.

Pleasant Grove '14 corner 14-15 #S 31406 (3)

Can't Make out Back

Gov't Notes

40.00 Set • 1/4 section post

White Oak 7 5 45 W 43

Aspen 10 N 44 E 49