/ 5-17-72 set C/M in place of small L stone. short iron below - stone by C/M. #531504 (1)

1/4 corner 15 - 22 Pleas Grove 105 - 13

6-1886 Hunter P410 no 399 L15 W Burgan, R Folsom. found stake & B T set by Freman 160 rods north center 22 as this was an "erroneous" way of setting a 1/4 corner run E-W section line and set "corner" M & L. 40.09. 2645.94

B trees - 6" L oak N61W 3 lks - 1.98'
6" L oak L26°W 7 lks. 4.62'

- 1/16 west set stake M & L 20.04 1/2 - set stakes every 10 rods.
6" white oak L18°E 26 lks.
6" " " L77°W 19 1/2 lks.

---

1-1894 W Fraser P543 no 504 L15 John Clark set found "corner" set P410 left as is

over)

1/16 north - set stone 3 x 6 x 18 M & L 19.90. 1313.4
B T 15" white oak S 63½° E 14 links (9.24'
also set stone & stake M & L 9.95 (656.7 between above
1/16 corner and S ¼ 15.

---

2-1896 H Fraser P 591 No 537 S 22. G Wolf, C Decker, M. Clark.
found "corner" P 410 still no desc. of corner.
- Meas south 39.56 to center sec 22. 26 11'

---

5-16-92 Co surv. meas from limestone found at Center 15.
found small elm, very decayed undesignatable corner, at
2626.1 R 2626.8 easily under fence top of stone down 1.3.
bottom of woven wire fence over at least 10" by field work.
5-17 set C I M. 176. N to PP pipe Cap W ends PP on slope.
- Meas east to ℄ Road 1326 - to 14-15-22-23 2644.6 R 2645.9

Pleasant Grove 1/4 corner 15-22 #531504 (2)

Govt Notes on Back

Geol Wells M.G. Karrick 1851 East Ramlon
1/0.06 Std temp Std post 1502z

West on true line between Std 1502
1/0.10 Std 1/4 Std post V 10°43'

Ashton C N70 E187
Jackson 7 S31 W170