5-15-72 found orig limestone. left as is set steel tie pp

#531509 (1)

1/4 Corner Center 15 Plum Grove 10 5-13

1-1894 St Fraser P 543 No 504 L 15 John Clark ext

set stone 2 x 8 x 24 at true intersection lines

BT. 6" white oak N 80¾ W 54 lks

4" hickory east 25½ lks.

-1/16 north set stone 2 x 12 x 20 M & L. 19.77 1304.72

-1/16 east set stake M & L 19.97 1318.

-1/16 south set stone 3 x 6 x 18 M & L. 19.90 1313.4 with

BT 15" white oak L 63½ E 14 lks. (9.24'

See 1/4 10-15 detailed plat adjacent survey.

OVER)

5-15-72 Co surv. found 1½" solid iron set by Mr Yates in place of old stake set by W Fraser as Center NE¼ 15 N&L on E-W ¼ line many years (likely over 50) RP's to rod. 40.83 W to ins edge Calv.

---

ran line from large corner post at ¼ E believed from 1968 meas to be correct N & S. over yates iron west. 13 17.36. set nail (1'@N) - meas south no line along Power poles. Could not establish any intermediate corners. - found perfect recorded limestone at Center 15. at. 1303.6 R. 1304.82. - set other L stones by corner with steel ele fence post by side of orig stone. - Corner 1.5 S of new woven wire fence in almost exact line of west edge huge power transmission pole. - meas south 13'13.4 a record. could not find stone this time. 5-16-72 found 1"x9"x12" L stone at ¼ 15-22 at 2626.1 R 2626.8 still cannot find by ¼ stone S of Center 15 or ¼ stone N of Center both gone.

#531509 (2)

Card # 2. Center 15 Pleasant Grove

2-12-72. reset 1/4 14-15 2623.5 south of section corner at 10-11-14-15, with 1/2" temp rod.
- offset 35' south at 1/4 14-15 and center 15. and projected line west thru woods. to iron rod at 1/4 15-16 as set. line fell 21.15 south of rod. or 13.85 short
- meas elect to 1/4 14-15 2636.04