#531606

3/8" rod set as corner in 1972 [redacted]

4-20-1964 set feldspar pipe with no cap (1)

1/4 Corner. 16-17. Pleasant Grove 105-13.

11-1886 Hunter P417 No 406 L 16 P. Redmond, Jr. Levan.
found old stake properly standing, tested it by NW BT.
standing and found it correct, left stake in ground

4-1895 Jr Fraser. P565 No 518 L 16 Chas Russell.
found stake as given in. P417. also B Trees. Geo Taylor.
- Meas L to property stake 25.07½ 1654.95
then L to " " 5.01½ 331.0
then L to section corner stake set. 10.03 662.0
Bearing. South L 1°W, North L ½°W. 40.12. 2647.92

11-24-1939 J Kerr. P546 B. fieldbook # 16 P57 L17
Page 57 entire page started at E 1/4 16 ran line Evans Chapel.
West - found limestone at center 16 in place. 5' south of line (over a ran.

Cont line west which fell 6' N of corner post.
- found orig B tree. next corner with square burr oak.
stake with shellrock packed around it. also broken
crockery and set boulder stone on top of same.
about 6' NWly of fence corner. - Witness trees -
68.9' S 81°15' W to center 28" elm tree
36.6' N 16°30' W to center 12" slippery elm tree.

11-28-39 J Kell P 546 B. L 17. field book 16 P 56 JP Chase.
started from 1/4 16-17. as set. ran S 6°45' E to corner
set as NE corner 20 - line fell 78.5 E of corner.
or 2574.04 corrected. R W Fraser 2647.92
should re-measure. (no corner to cross).

1962 Co H D. used boulder 2 1/4 x 1 1/4 x 1 1/4 center 6 diam - 35.00.
Orig govt notes 16" elm. S 88 W 104 lks Root runs 75 lks W to 4618
9" ironwood S 17 E 120 lks 79.2 runs NE.

Card # 2. 1/4 16-17 Pleasant Grove 105-13. (2)
4-24-72. found iron rock set by J Kerr 11-1939 P 546B.
set 321.5 North of square bolt set as SW 16 from BT
a 12" white pine S 33 W 157 lks 103.6. on stay slope.
Cont line north on various offsets until station 1285.8.
- found large badly bent pipe in brush pile at 643.4 WF 662.0
- found angle iron up 30" + at 965.1 WF 993.0
- found steel fence post at 1285.8 #531606
abandoned present random offset 2.0' E of above 2 iron posts.
- found post steel fence post at 1607.8 line 2.15 E of line
offset back west 2.0 feet to orig line.
- found steel fence post at 1768.8 line now .25 E of post
- found 4' high 1" iron post at 1929.8 line now .30 E of iron
- Cont to p.o.t. at 2229.8 nail.
- Cont to 2573.7 - found no stone but drag tooth and Crockery
set elec fence post with 10x12x16 boulder on downhill sign & track
2647.9 w/l Fraser rec dat 2573.7 is 74.2 N rec-

1/4 16-17 10 5-13 Corner set almost exact to J Kerr corner. but the mean difference of 74.2 can't be overlooked - best and only way to really check is line from west using west line 17 set by mean and occupation lines of road at N 1/4 17. Nothing 1/16 fence lines E & W and see how it doubles on 1/4 fence at Center 17 close to road when project it east.
a huge power pole servicing fancy homes in woods at 1/4 16-17 Can be seen from west. it lies ± by eye only. 35.68 west and 21.78 south of. POT nail 2229, & station or ± at station 2208 or 365.7 south of. J Kerr corner which lies 5.5' E of buried iron with roundtop and 6' NW of corner P.

Govt Works by M. G. Karrick 1851
40.00 Sta 1/1 Sta Post
Elm 16 5 & W 10 1/2
10 in Wood 7 S 17 E 17 e

1/4 Corner 16-17 Pleasant Grove 105-13 (3)
#531606
Page 4 No. 7

May, 1856 Thos. Hunter Shows 1/4 post
1/16 North 20.06 chs. M&L
1/16 west 20.63 chs. M&L To center Section
Small Tract on S.E. 1/4 Sec. 17

4-20-1984, 1/4 Cor 16-17 : Set telspar pipe over 3/8" iron set in Feb., 1973. The pipe was crushed on top from driving so did not use cap
RP: Spike & C.S.D. in 10" Elm SE 18.27

