#531706 (1)

1/4 corner 17-18 Pleas Grove 105-13.

5-1856 Hunter P 3 no 6 S 18 east 1/2

used corner- set 1/16 cor north 20.07 2 B trees · M & L
(@ 86½° W 249 links) & (S 78° W E 302 links)

set 1/16 south 20.07½ 2 B trees M & L.
(N 69½° W 139 links) & (N 69 3/4° E 75 links).

5-1856 Hunter P 4 no 7 S 17.

used corner - meas north 40.14 - meas south 40.15
- meas east 39.73. 2622.18

6-1886 Hunter P 11 no 400 S. 18 Henry Pruitte

Corner gone - found. 1/16 corners north & south P 3 no 6.

set stake as 1/4 corner from these corners (over)

Meas north and south to 1/16 corners. 20.07. 1324.62
"run & meas line from CIM at SE18 north. checking ℄ road.
Maybe likely post at 1/4 corner land always common on both sides and mostly terminal at 1/16 prop fences N of 1/4 17-18.
3-6-13 see traverse center 17.
dug 3'x 5'x 4' deep near computed M&L for 1/4 16-18 found definate post hole about 1'W 4'N set 6' long brush stick in hole- set 1/2" x 2' pipe as near M&L as possible without transit. area in deep wash delta between 2 farms.
Govt Notes M.C. Harick 35 1/
40.00 Std 1/4 Std post
Bur Oak 12 S 33 W 132
" " 13 S 5 1/4 E 111

1/4 Corner 17-18 Pleasant Grove 105-13 (2)
#531706

9-26-96 Found Pipe Set By R.B. in 1973 Found By V.F. in 1996 1' SW of CP To Fence N-S-E. Will Traverse To Verify Position Before Setting Final Corner.

9-27-96 After Traverse Dug + Dipped For Pipe Set By R.B. in 1973 13.07' South Of Pipe Found By CP To Fence N-S-E. We Dug 2' Deep In Fence + Burnt Out Roots + Brush. We Dion't Get A Dip Or Find Rust. If This Was A Ditch Area As Stated By Merrit P. in 1973 It Is Hard To Figure What went on Here. The Pipe By The CP is A 1/2" Pipe With Union On Top 2' Long. This Area

9-27-96 CONT: IS A FILTER AREA FROM WEST.

10-1-96 - VINCE FANGMAN SET 30" TELSPAR W/ NO CAP AS CORNER. FOR SURVEY IN SE¼ SECTION 18. ↑

RP's NAIL + BOTTLE CAP IN WEST SIDE 6" ELDERBERRY NNW 26.00

NAIL + BOTTLE CAP IN WEST SIDE CREOSOTED BRACE POST N 21.50

½" PIPE ON WEST SIDE C.P. FENCES N-S-E N 13.12 (REMOVED)

NAIL + BOTTLE CAP WEST SIDE TREATED BRACE POST FENCE EAST NE 15.73

VINCE SET CORNER AFTER COUNTY SURVEYOR CHECKED HIS TRAVERSE. AND DISCOVERED THAT THE ½" PIPE FOUND BY BOTH VINCE + CO. SURV. TO BE TOO FAR NORTH.

6-13-97 FOUND TELSPAR SET BY VF IN GOOD CONDITION. @ COUNTY SURVEYOR ESTABLISHED LOCATION. SET POST + SIGN ½' E.

#531706 (3)

1/4 CORNER 17-18 PLEASANT GROVE 105-13

11-19-97 SET CIC/P^2 IN LARGER V.FANGMAN PIPE AS FINAL CORNER WEST SIDE N-S FENCE + 13½' SOUTH OF FENCE EAST.