#532105 (1)

8-4-1964 set C/M over 1¼ x 18" pipe

section corner 20-21-28-29 Pleas. Grove 105-13.

no records.

10-1941 J Kerr B26 P37.

run north line section 28. accepted large stone south of corner post as corner claimed set for corner.

- meas east 2632.62 to steel pipe set M & L.

8-1964 J Kerr setting corners. (Cut)

replaced large stone with C/M over 1¼ x 18" pipe which proved on original line.

Steel fence post south 0.5'

120 D m lone burr oak in fence line east 108.7 over)

Corner lies 2' west and 3' south of fence corner.

E-W-N.

No fence south.

corner lies slightly above surface.

2-6-1973 ran electronic traverse to corner, found fence going east gone and farmed as common field N & S. steel post smashed flat, big tree pushed into low drainage area SW of corner 100' or so. C/M still in place, corner post north gone. Corner in exact line of fence north - drove 40D nail on E side 6" boxelder 2' west of fence north 11.25 from center C.M. Corner should survive if lands NW of corner remain one separate property

Pleasant Grove Section corner 20-21-28-29 (3)
#532105
Coord Notes on Book

6-13-1979 Visited Corner. Found C.I.M. with steel fence post up 2' on SE side. Set a survey marker sign 2' South. Found the 40d nail in the East side of the Bot Elder North, now being used as the end post of a new fence going north.

4-20-81 Sec. Cr. 20-21-28-29: Farmer Schram is removing fence and requested monument to be removed. Dug out CIM and shot 1¼" pipe beneath. Also removed 14" x 6"/14" x 24" limestone standing on the North side of the CIM. Set a 3' teleper with CIC as the corner deep to be below the plow. The corner is in line with the fence to the West. The fence North and the fence West near the corner are gone.

Gov't Watts M.C. Karrick 1841

80.00 Std post for corner to Std 20, 21, 28, 29

Bur Oak 15 in S & W 271

Dug Iron 6