2-20-73. set 1/2" rod as final corner -
X 7-79 Set CIC/p* #532106

1/4 corner 20-21 Plum Grove 105-13

11-1883 Hunter P386 no 377 S20 E. Cole etal.
found unmarked stake, tested B trees still standing and found incorrect, reset stake correctly by Govt notes.
- Meas north 27.00 to stake NE 20. on sec line.
- Many plats in NE 1/4 20.
- Meas West 19.92 1314.72 To 1/4 with many wooded corners Ltw.

11-1939 J Kerr P542B B16 P57 S20 E Chase.
fence post on south side of lane accepted as corner.
- Meas north 2628.38 to iron as sec. corner.
- 1/16 west set iron 1337.05 M&L rough & river too.

Orig. govt notes 8" Blkoak N64W 49 lks. 32.34
14" wht oak S70E 104 lks. 68.64

2-20-73 found 30D nail set by McGhee just north of Corner post of fence E-W-S - set ½" x 2' rod .9S and .6E to best fit electronic traverse calculations for corner.

- corner just east of corner post.
16.7' SWly to 60D nail on NW side 6" ash up 2'±

Gov't Notes M.G. Karrick 1854
110.00 Set ¼ Stone P-St
Blackoak & Hickory
White Oak 14 S 70 E 104

7-1979 Replaced ½" rod with CIC/p². Corner on East side of corner post to fence East and South.