1 7-10-72 found stone set elec fence post as temp cor.
7-23-82 set CIC/p2 - in place of elec. fence post
#532304

1/4 Corner 23-26 Pleas. Grove 105-13 (1)

4-1895 H Fraser P563 no 517 S23 J. O'Connor, H Burgan & Lourie

Corner lost, no evidence, knowledge or B-lines

set stone 3 x 3 x 22 with stake by side M & L. 39.83 2628.78 S88°W

1/16 west set stone and stake M & L. 19.91 1/2 1314.39 S88 1/4° W

1/16 north set stone and stake M & L 19.90 1313.4 N1° W

1/16 center SW 1/4 S23 set stone and stake at inter. lines

7-10-72 easily found exact size limestone 18" ± S N

A new corner post & fence N of this and west:

Set elec fence post to center over stone (down 20" ±)

and set standard steel fence post near stone & rod.

corner lies slightly west of fence running north and a little south of fence running west.

- Meas west To 1/16 fence running north (1310+) R 1314.4 M&L.
- Meas west To stone and C/M at 22-23-26-27.

2627.0' R 2628.8.

dug very extensively at 1/16 fence west, found nothing, set nothing, should be at least up to 3' W of fence X. there was an arrow shaped stone with 10" base pointed about 12" long lying near corner post which could have been corner which could be up to 3.5' W of corner post.

Govt Notes M.G. Harris 1851 EMSL Random T3+2E
40.00 Std temp Std post
W731 on true line bTWTTM Std T3+2E 10° 39'
39.93 Std 1/11 Std Post Bur Oak ? 3 to W 300 lks
" 10 N 17 W 170 lks

#532304 (2)

¼ Corner 23-26 Pleasant Grove 105-13

7-23-82 ¼ Cor 23-26: Found the electric fence post set over stone in 1972. Drove CIC/p2 over electric fence post. Left CIC up .3. Corner 15" West of the c.p. to fences E-W-N-S. A steel fence post stands ESE .4. Nailed survey marker sign to corner post.

R.P.: Spike in N. side c.p. ENE 1.37