X 11-20-1967 CIM set by Co Hwy dept. #532409 (1) of 3

1/4 Corner Center 24 Pleas Grove 105-13

6-26-70 pulled CIM set ½ rod.

9-1885 Hunter P 403 No 392 S 24. S Lowrie, J. French.
set stake at inters lines. 8" D. oak N 27°E 46 lks.
8" D oak S 44 3/4° E 39 1/2 lks.

1/16 north set stake 19.86 1/4 M & L. (1310.92'
1/16 south set stake 19.85 3/4 M & L. (1310.6
1/16 west set stake 20.00 M & L. (1320.0
1/16 center S W 1/4 24 set stake inters lines
1/16 center N W 1/4 24 " " " " also
1/16 set stake south above 1/16 M & L 9.96 1/2.

12-1874 T.H. P. 265 BK A NW 1/4 24

(over)

1938 Co Hwy Dept. found stone set pipe xjoer.
B 96 P 2 dug found pipe W side limestone used pipe as corner.

S. edge flag pole	N.W.	94.3
near edge steel fence corner	S.W.	43.5.
spike in 10" spruce	N.E.	58.35

Meas North 2620.3 R 2621.8

11-20-67 Co Hwy Dept set C/M over above point.
additional R.P. - spike power pole S.W. 61.58.
B96 Meas south 2617.7 R 2621.2
cross in SE corner well foundation NW 93.21
Disc in telephone pole NE 61.87.
1967 Meas. south - 2616.43 north - 2618.39
PI 0° 2½' right going north.

#S32409

Card # 2 Center 24 Pleas Grove 105-13 (2) of 3

6-26-1970 Co. surv. found CIM set by Co. H. Dept removed. set 3/4" x 12" rod below and 1/2" x 2' rod as temp cor.

RPS. Disc in power pole # 13229.	SW	61.58
Disc in tele pole	NE	62.02
punched cross in north end road culv east	NE	39.84
" " " south " " " "	SE	39.5

7-19-1982, Center 24: Dug with backhoe from a point 1' East of the 1/2" rod in ℄ Co. Rd 19, East for 3', North 2', and South 2'. Fill to clay. Found nothing.

7-22-1982 Q 1/16N: Dug with backhoe centered over a point M+L between the CIM @ the N1/4 24 to 1/2" rod @ Center 24. Area had been cut to clay appox 3' deep, but we did find a rust hole from an Iron or pipe appox 1" diameter in the clean clay.

mark { C.M. W 4.65 C.M. N 6.35

7-21-1982, 1/16 South: Found fences East and West midway between the 1/2" rod at the Center 24 and the iron at the S. 1/4 Cor 24. Dug thru 9' of fill to clean clay. Found nothing

7-30-1982, 1/16 South: Dug for Hunter stake set 100 lks. West. Dug under fence West only. Pt. came where pipe track to c.p. was cemented in. Found nothing

8-17-1982, Center 24: Set a 1" sq pipe/cap 1.72 East of 1/2" rod (removed) in place to be at the intersection of the line from the 1/2" rod to the E 1/4 Cor 24 and the line from the N 1/4 Cor 24 (CIM) to the S 1/4 Cor 24 (CIC/P² as set this survey). This corner 1 1/2' E. & N-S road and 1' North & roads E. and W.

RP's: Punch hole N. end C.M.P. in road E. NE 38.32
Punch hole S. end C.M.P. in road E SE 37.94
Punch hole S. end C.M.P in road W SW 43.19
Punch hole N end C.M.P in road W NW 41.85

Center 24, Pleasant Grove 105-13 (3)

#532409

8-17-1982: 1/16 N Set a 5/8" smooth rod with cap midway and on line between the N1/4 24 and the Center 24 (1"sq. pipe/cap set this survey) 1.41 So and .89 East of the rust hole found here 7-22-82. Corner 4' South of fence West and 1' South of fence East and 3½' NE1/4 & Co. Rd 19 on curve NW1/4, and ½' E. & road further South.

RP: CSD So side pp# 41199 WNW 50.85
Punch hole top So. end C.M.P. in field
drive East SE 46.14