X 8-13-82 Sect C#10/p2 #532504 (1)

In Hwy 30 - 3/4" rod in place - orig'n unknown (could be Co. Hwy D)

1/4 corner 25-36 Pleas. Grove 105-13.

9-1885 Hunter P401 No 391 S 25 J Tait, J Baker, J French D Brown.

see ToH. fd BK 14 p 49-50

found stone center road, set by Mills - surveyor from Pl. Grove.
set from stake when all B trees standing. N E B T still standing
N 46 1/2° E 236 lks = 155.76 burroak. (orig Gov't Notes = N 60° E 235 lks. to Oak

1315.38

1/16 east set stone 19.93 M & L. N 88 3/4 E

1/16 north set stone 4x5x15 19.95 M & L. (1316.7'

1/16 center S E 1/4 25 set stone at inters lines

1326.48

1/16 west set stone 5x6x12. M & L 20.09 3/4. N 88 1/2 E

1/16 center S W 1/4 25 set stone inters lines

Co. H.D. BK 48 P. 9 8-1927.
Possibly 1/4 Cor. - Stone + stake with R.P.'s
10" cedar Tree - NE 49.2 —— 14" Maple Tree - SE 66.75

over.

Co Hwy Dept.
found stone - 3/4" x 24" iron riser.

24" maple ∠E 40.48 — 10" apple ∠W 60.19.
B 96 Page 1 24" maple ∠E 52.8 — 3rd apple tree SW 93.9
1" pipe assumed Center over 1/16 S. cor fence post ∠ 30.9

1/16 corner north - between center 25 and ∠ 1/4 25

Co Hwy Dept. B 96. Page 1 (Level with top of road 1/2 way between two Cor. Fenceposts.
found limestone 4"x5"x15" ~~no RPS no date~~. probably CO.H.D. #38 Comet

Minn St Dept found 1" pipe in place. 2631.6 north to center 25.
Sta PI 479+30.0 Tree 25 maple 58 42.0 10" apple SW 58.2
Δ 0° 3' right going east 2652.0 west to iron pipe mk.
angle (west to north) = 89°42'

1938 - C.H.D. Book #96 page 1 Dug a hole 5'x4'x3' and found nothing. Set a 1" pipe on line from Center 25 over 1/16 Corner South at 1315.8 in each half. (! book 307)

Plaistow Corner 25-36 1/4 Cor. #532504 ②

LRP } CN No. 16
3/4" iron } Sp. W 9.01

Cole's Notes — Back

11/26/80 1/4 Cor 25-36: Dug from 3/4" iron found at surface of blacktop, North 1', South 3', West 2', East 7'. Found another 3/4" iron beneath the iron in place and down 1½'. Fill to clay 4' deep. Found nothing except where someone had dug across the West end of our hole. They dug to about 1' East of the irons.

12/8/80 Set 5/8" rod back at P.I. location for NHD.

12/1/80 1/16 East: Dug from traverse nail set on line from location of 3/4" rod at 1/4 Cor 25-36 to the stone location at E. Sec. Cor 25-36 and in line with the fence South, North 1', South 2', and West appx 6'. There was 3' of clay fill on clean clay. The area appeared to have been subject during road

Cor's Notes M.G. Karrick 185'± East Random
40.00 Std temp 1/1 Std. post 25-36
West on true line Bryan Stds 25-36
40.00 Std 1/1 Std post 10° 33'
Bur Oak 7 S 20 E 380 = 250.8'
" " 7 N 60 E 235 = 156.10'

Construction. Found nothing LRP's tn } E 6.74
S 7.5±

8-2-1982, 1/16 North: Dug for and found old C.H.D. hub 1' North of fence West and 74.91 West of rod in E road. The East hub would now fall in cultivated field and we did not look for it.

8-13-1982 1/4 Cor 25-36 & Set a CIC/p² at double the line and measure of the 1/16 West after correcting Sec. Cor. 25-26-35-36. The corner is .4 N & To H. 30,

#532504 (3)

¼ Corner 25-36 Pleasant Grove 105-13

8-13-1982, ¼ Cr 25-36 Continued: 5' East & C.R. 19, and 3½' East of the line of the fence South.

R.P.'s; CSD in E side pp # 13095 SSW 71.50
Mn/Dot Disc in SW side pp # 40600 NW 88.30
Mn/Dot Disc in SE side pp stub with telephone boxes NE 79.13. Corner is 2.76 East and .15 North of the Mn/Dot P.I. Mark.

8-13-1982, 1/16 Note: Set a 5/8" smooth rod/cap .53 So. and .34 E. of ¾" rod in place (removed) to be M&L between the Center 25 (Fd) and the

S 1/4 Cor 25 as set in this survey. The Corner is .3 East of ℄ C.R. 19 and 3' South of the line of the Fence W (Fence East now gone)

RP's:

CHD Disc in NE side pp #13202
NW 63.70

Punch hole N. end CMP in field drive NE 45.55-