X 6-26-81 ~~Set CIC~~ 1982 Corrected CIC #532505 (1)

In Hwy 30

section corner 25-26-35-36 Pleas Grove 105-13.
9-1885 Hunter P401 No 391 & 25 J Fait J Baker J French.
found stone with stake by side in center of road, D Brown.
claimed set carefully by old settler where orig corner stood.
accepted corner as correct.

1/16 north set quarry stone M & L. 19.99½ = 1319.67 S 1°32' E.
1/16 east set " " 5x16x12 M&L 20.09 3/4 N 88°30' E.
1326.43
1/16 center SW¼ 25 set quarry stone at inters lines

T.H. 30 R/W map 1950's - I.P. in place as Sec. Cor.
P.I. 453+18.2 Δ = 0°07' RT from West

(over)

Co Hwy Dept. (Bk 48 p. 9) ? find no sweet description

1" pipe by 1/2" x 8" spike.

Co HD. Bk 48 P. 9

corner fence post	N	31.65	33.55	state Hwy map
tele pole	NW	46.47	44.75	
origin of ties unknown 14" spruce	SW	46.45	46.45	Co r F.P.
Cross in base Conc Cor post	S W	46.3	B 48 P 9 (1927)	

Govt Works M.C. Karrick 1951

80.00 Std post in Mound with brass pins and charred stake planted Osage orange stakes at each angle for corner stations 25, 26, 35, 36

#532505 (2)

Section Corner 25-26-35-36 Pleasant Grove 105-13

11/26/80 Sec. Cr. 25-26-35-36: Dug from 3/4" iron found at surface of blacktop West 2', South 2', North 2', and East 4'. LRP } CN West 7.92 .04 N
CN South 7.50 ±0.05 E

Found a 3/4" x 18" iron down 18". LRP } CN W 7.88
CN S 7.50

Dug further and found a 3/4" x 2' iron 2' deep. LRP CN W 7.79
CN S 7.51

Found nothing further. Dug down 4' to clay. Area .13 W
appeared to have been subject. .09 N

12/8/80 Set 3/4" iron back at location of P.I. iron found at surface of blacktop for M.H.D.

12/1/80 1/16 East: ~~Dug from traverse nail set on line from location of 3/4" rod at 1/4 Cor 25-36 to the stone location at E. Sec. Cr 25-36 and in line with the fence South, North 1', South 2', and West about 6'. There was 3' of~~

clay fill or clean clay. The area appeared to have been subject during road construction. Found nothing.

LRP's to t.n. } E 6.74
S 7.54

1/16 East

12/2/80 ~~1/16 West~~ : Dug from traverse nail set 11-1977 West 2', North 1', South 3', and East 6'. Found Hunter recorded stone standing in black dirt 5' deep and appx 1.05 N and 2.70 East of the traverse nail

LRP t.n. } c.n. W 3.65
c.n. N 6.3

Stone } c.n. 6.4 W
c.n. 5.85 NW

12/8/1980 : Set 5/8" rod iwtt cap over stone found.

RP's CSD SE side pp# 13085 SW 95.98
Punched cross in lug at E. end CMP in field drive SSE 38.81
Corner in ℄ E-W road and in line fence N.

#532505 (8)

Section Corner 25-26-35-36 Pleasant Grove 105-13

6-1-1981 1/16 North: Found stone 3" x 6" x 12 tilted North Set 5/8" rebar where stone sat 5.6 North & 1.10 East of Trav. Nail. Stone is beside iron.

6-26-1981: Set CIC/P² at double the line and measure from 1/4 Cor 25-26 over the 1/16 South (found), Corner came .15 South and 1.17 West of MHD POT Iron in ℄ T.H. 30, and 1½' West of Fence line North and ℄ road South.

RP's: Punch mark West side 2" pipe Corner post SW 81.40
MHD Drive in West side rp #1906 82.66 SE
Punched cross in lug at top, West end CMP in Field drive NW 46.05

8-13-82, Sec. Cr. 25-26-35-36: Pulled CIC/p2 and reset at Mn/Dot P.O.I. location 1.17 East and .15 N as the corner. Corner in ℄ T.H. 30, in line with fence North, and in line with ℄ road South.

? 1'E in 1981

RP's:

Punch mark West side 2" pipe corner post SW 81.99

MHD Disc in West side pp# 13068 SE 82.24

Punch cross in lug at top West end CMP in field drive NW 46.52

(we accepted the Mn/Dot point here as correct after finding the corners at the West line of Sec. 25 as set by Hunter and fd by us. (NW, W1/4, and 1/16 S. of W1/4) are not on a straight line.)