X 11-20-67 set C/M over old point #532509 (1)

C/M pulled 6-26-72 [illegible]

1/4 corner center 25 Pleas. Grove 105-13.

9-1885 Hunter P401 No 391 & 25 L. Tait, J Baker, J. French D Brown.

set stone 5 x 6 x 20 at true inters lines.

-1/16 east set stone for line &. M & L 19.96 1317.36 S 89° 32 W

-1/16 west set stake " " &. M & L 20.04 1322.69 11

-1/16 north set stone 6x7x20 M & L 20.05 1/2 < well down. 1323.6

-1/16 south set stone 4x5x15 M & L. 19.95 [1316.7

-1/16 center & E 1/4 25 set stone inters lines

-1/16 center & W 1/4 25 set stone inters lines

all stones quarry limestones.

over)

1938 Co Hwy Dept B96 P1.

found stake & stone — Meas north to stone found 1323.7
20"x6"x5" 12" dup & 3/4"x2"x ? iron R 1323.6
set 3/4" x 24" iron riser. by tape.

Sp hg willow N.W. 56.4 Meas south 1315.8
R 1316.7

" " " WNW 102.3

" 3RD fence post west of corner post WSW 72.7.

PI at center 0°4' lt going north.

1938 Co Hwy Dept - 1/16 corner between Center 25 & N 1/4 25.

Book 96 found limestone — 1967 RPS — pretty shaky — Sp tele pole NE 75.23

Dice cor fence post E 59.85 - Dice power P. SW 81.2

1967 - set CIM over Center 25 - B 307. Meas to a PI at

Dice tree NW 93.43 center 25 0°4½' lt going north.

" PP NE 121.49

" TP ESE 61.45

#532509

Card # 2 Center 25 Pleasant Grove 10 5-13 (2)

6-26-70 Co surv. found C/M. set by Co H.D. 1967.
removed C/M. set iron below with ½"x2' temp iron cor.

Co RPS. Disc in tree	N.W.	93.43.
Disc in power pole.	N E	121.49.
Disc in tele pole	E S E	~~61.45~~ gone 1982

New RPs.

punched cross in notched end 18" galv culv	W S W	37.18
" " " North " "	N W	44.88
Center large steel corner post in Concrete	N W	49.88

7-20-82, Center 25: Dug with backhoe on West side of ½" re-rod at road surface. Found recorded stone down 4" and beneath rod. There was a short 5/8" re-rod over the stone. Set this rod on West side of the stone and set the ½" re-rod back at the road surface.

CRP 6.3kW 7-95

7-21-1982, 1/16 North: Dug on East side of rod in place. Found fill to dig 3' deep. Left iron in place.

8-13-1982, Center 25: Removed ½" rod and set 1" sq. pipe with cap in its place. Corner 7' South & rd. West and in ℄ C.R. 19.

R.P. CHD. in SE side pp#40604 NE 121.41
Punch hole top S. end C.M.P. in road West WSW 37.25
Punch hole top N. end CMP in road West NW 44.90

8-13&17-1982, 1/16 North: Set a 5/8" smooth rod with cap 1.28 South and 1.24 East of 30" drill steel (removed). Corner witness and on line between the Center 25 and 1/4 Cor 24-25 as set this survey. Corner in line with fence East and 1' South of fence West, and 1½' East of ℄ C.R. 19.
RP: CHD Disc in pp# 13213 SW 80.76
Punch cross N. side pipe corner post West 57.91

1/16 corner between Center 25 and south 1/4 25 Pleasant Grove 105-13
1/16 corner

9-1885 Hunter P401 no 391 L 25 Tait, Baker, French, Brown.

set stone 4x5x15 N&L 19.95 (1316.7' Precede Center 25

1938 Co H D B96

found L stone 4x5x15 at road surface about midway

Fetw corner posts opposite each other.

- Meas south 1315.8

1967 B 307 P2

found above stone above set C.M.

- Meas from center 25 to 1/16 stone S. 1315.08

1/16 corner now PI with angle of 7½° left going north over RRs.

Disc	in fence post	NE	68.99
Disc	in Cor fence post	E	60.17
Disc	in " " "	W	60.12
Disc	in power pole # 13202	NW	63.30

New Tie 6-26-70 when CIM removed.
set iron in place of CIM. (No CIMs at 1/16 corners) extended
punched cross in S. end 18" fill drive culvert NW 59.87
" " " N. " " NE 45.48 extended

1/16 corner between Center 25 and North 1/4 25. follow Center 25
1/16 corner
Pleasant Grove 105-13.
9-1885 Hunter P401 No 391 S25 J. Tart, J Baker
F. French, D. Brown.
set stone 6x7x20 M+L 20.05½ (1323.63'

1938 Co H.D. B96
found stone 5x7x20 broken in 3 pieces which came
1.5' west of line from 1/16 corner south of Center 25 over
stone at Center 25 put nail in stone
- meas from stone at Center 25 1323.7'

1967 Co H.D. B307. found hub and stone - set C/M.

RP (over.

1967 RPs. Disc cor fence post E 59.85.
Disc in tele pole NE 95.23.
Disc in power pole. SW 81.2
Meas from center 25 1323.76' then 1323.21' to ¼ 24-25

6-26-1970 Co surv. found C/M set as corner.
New tie Center 2½" steel corner post. W 56.65
removed C/M. set long, large drill steel rod as corner.