5-31-78 CIM

#532705 (1)

section corner 27-28-33-34 Place Grove 105-13
8-1902 OH Case P45B. copy of survey made sent to W Fraser.
Run line from SE 33 to E 1/4 28. set 1 1/4" x 40" pipe and
stone 4" x 16" x 16" on north side which came near brass post
as claimed by a Mr Rider owner of N 1/2 of NE 1/4 33.
- Meas south 39.98 2/3 to 1 1/2" x 40" pipe set as 1/4 cor M & L.
80

7-1930 Co H D B 57 P 43. found pipe stone as recorded.
on east side corner past.
Meas west 5280.6'
Meas south 5274.4 to 1/4 33-34. 2639.8

T.H. 30 R/W map 1950's Shows Meas. of 1883.0' South
To & T.H. 30 at P.O.T. 292+15.1 no indication of what
was used at this Sec. Corner

Govt. Work M.C. Karrick 1854
80.00 Std post in Mound with trench pits, ~~Orn~~ chgrd. stakes and Osage Orange sticks planted at Each Angle for corner sections 27, 28, 33, 34

4-11-1978 Found the stone and pipe recorded by O.H. Care down 6" and 2' S.E. of the corner post to fence E-W-S. The base of an old post was on the West side of the stone.

5-31-78 Drove Case's pipe down and set a CIM over it.

8-10-1979 Dug at double the line and measure from the stake found a 1/4 Cor 28-33 over the corner post at the 1/16th East. This point came appx 10' West of the CIM @ 27-28-33-34. (continued)

#532705 (2)

Section Corner 27-28-33-34 Pleasant Grove 105-13

(continued) We found the remaining 2' of a post of appx 7" diameter - top down 2' = 9.35 West of the CIM. Drove a 5/8" iron down through the center of the post stub and set it back at the location it was found - could not be sure this was not just an old post in the E-W fence line. Dug from the post stub 1' North, 1' East, 2' South and 3' West but found nothing further.