X 8-23-82 CIM #533206 (1)

1/4 corner 31-32 Pleas Grove 105-13.

5-1893 H Fraser. P528 No 493 S 31-32-33, E North
C H Ited
C Bruster.

Could find no corner-
set stone 3x9x27 M&L 39.94.
-1/16 south set stone 3x15x18 M&L 19.97.

4-1942 J Kerr B27 P4.

used corner to set center 32 M&L 2637.62. no meters lines.
1 1/4" shaft casting with no AD [redacted]. 640 set over Corner found
Sp 18" burr oak N 39°45 E 97.0'
" turn oak N 64°10 E 116.0'
" measured North 2634.75-

7-1930 Co HD B57P7 - found 6x3x24 LS with cedar hub 9" south of stone - used stone as true corner"

Govt Notes M.G. Karrick 1851

40.00 Set 1/4 section post

Bur Oak 12 N 70 W 5.6

" " 13 S 27 E 16.6

T.H. 30 R/W Map 1950's - indicates 1/4" iron shot in place 15.8' North of ℄ P.O.T. 184+83.05

Meas. East To accepted Cor 31/32 2635.75

12/5/80 1/4 Cor 31-32: Dug from a point 12' North of T.H. 30 P.O.T 184+81.8 in ℄ (Same as N. edge blacktop) North 5', West 4', and East 4' by 4' deep to sandy subsoil. Fill to clay. Entire area had been subsoil. No evidence of Iron or stone

Set 1/4 Cor

#533206

1/4 Corner 31-32 Pleasa Grove 105-13 (2)

8-23-1982, 1/4 Cor. 31-32: Set a CIM over a 5/8" x 18" re-rod midway and on line between the section corners by e.t.c. Corner falls on N. shoulder T.H. 30 17.3 N & and 1' West & Crushed rock road running South, and 30' East of & driveway running North.

RP: P.K. in top N. end concrete culvert

WNW 52.73.