X 8-23-82 CTC/p2

#533306 (1)

1/4 corner. 32-33 Pleas Grove 105-13.

5-1893 JV Fraser P528 No 493 S31-32-33, E North, C Whited
C Bruster.
could find nothing - set stone 4x8x21
M & L 39.94 1/2 (2636.4' on N-S section line.

4-1942 JKerr B27 P4.
set plow lathe M & L 2633.9. RPs at that time
now Highway 20 rebuilt. check for state corner.

Co Hwy Dept. ~~stone~~ 1/2" x 9" spike. BK 57 P.44
40" willow N 51.23 Sp F P N 37.8 Hub L N 47.9
12" " NW 62.23 Hub L E 47.4 (all gone likely)

7- 1930 Co H D B57 P44- found stone
5.7 south & old P.I. RPS ap cor FP N 37.8
Meas. east 2642.3' To center 33
Meas north 2633.2' To NW 33
Meas south. 2635.2' To SW 33.

Govt Notes M.G. Karrick 1954
40.00 set 1/4 sec. post in Mound w. 4 trees & pits & stake planted. / Osage Orange stubs N.E. & S.W.

T.H. 30 R/W map - 1950's shows Plow share in place as 1/4 Cor 7.4' N. of P.O.T. Sta' 237+55.5 evidently Kerrs Corner. (Co. H.D. 1930 shows stone inplace but not exactly midway)

¼ Corner 32-33 Pleasant Grove 105-13

12/4/80 ¼ Cn 32-33 & Dug centered on "dip appx 7' North of POT Sta 237+55.2 in ℄. Found Kerr's plow-share 3' deep 7.52 North and .3 East of P.O.T and Will Fraser's recorded stone 7.27 North and .7 West of P.O.T or 1.0 West and .25 South of Kerr's corner. Stone 5' deep. Put the plow share on the North side of the stone and a ¾" iron on the South side. Set a ½" iron ~~on the South side~~ at the road surface over the stone. This corner in line with fence South and 3' East of fence North.

RP:- Punched cross in lug a top E. end C.M.P. in field drive NE 44.70

- CSD in SW side pp # 15021 NW 99.60
- CSD E side corner post NNW 64.66

plow share } 5.81 E, 4.71 S

stone } 6.80 E, 4.5 S

[redacted] 1/4 Cor. 32-33 Pleasant Grove #533306 105-13

(2)

8-23-1982, 1/4 Cor 32-33: Dug up the 1/2" rod set 12/4/80. Drove CIC/p² down over it. The corner is 7.36 North and .73 West of the Mn/Dot P.O.T. and 8' North of ℄ T.H. 30.

RP's: CSD in SW side pp# 15031 NW 99.54

CSD in E. side corner post NNW 64.65