8-4-1964 set CIM over 1¼" pipe. #533406

¼ Corner 33-34 Pleas. Grove 105-13

8-1902. OH Case P45B copy of survey made sent to H Fraser.

set 1½" x 40" iron pipe ~~39.90~~ 39.80 2/3 M & L.

8-1964 J Kerr placed CIM to preserve corner. over pipe found recorded 1¼" pipe. (down 1 foot)

Disc in new treated brace Post SSW 31.5'

" power pole N 30.8'

" tele pole ESE 88.7' = gone

Corner ~~lines with fence north~~ 3.7' E. of fence N. also

" lies 3.7' east of fence running south

" " 2.0' north & traveled road E-W.

7-1930 B 57 P 44 Co H D. found iron pipe recorded.

Meas south 26 36.6 to ∠ 33-34.
Meas west 26 29.8 to center 33
Meas north 26 39.8 to NE cor 33 a pipe

Govt Notes M.G. Harrick 1854
40.00 set 1/4 sect post in Mound
with iron pits, charcoal stake
and planted Osage Orange stubs
N.E. & S.W. of track

6-2-78 1/16th South. : dug 3'x3' on the Southeast side of the traverse mail by the corner post, but found nothing