11-27-1963 set CIM over pipe & stone. #540205 (#1)
section corner 2-3-10-11 Tri Forest 105-14.
6-1876 Hunter P299 No 294 L3 M Shanrahan, J Linaugh
corner stake now missing, but corner post & division fence.
running north between John Lenaugh & John Mc Elgan was
set by side of stake in mound. seen few years past by Hunter.
-16 west set stake marked M & L 19.96 (1304.16'

11-1887 Hunter P423 No 412 L2. John Griffin.
found corner post still in mound P299.
-16 east set marked stake direct aerial line M&L 20.16
B north N 3/4° E east N 89° 40' W.

11-1907 Ch Armstrong P110 B L1-2-11-12 J Kelly, R Thomas & many others
found stub recorded post set stone L S 4x12x18.
came 4 3/12 lks. east & corner. J. Linaughs fence!

- meas north 39.84 south 39.89.
- 16 east set stake M & L 20.16

---

stone found & used in survey 3/4" pipe riser set.
11-27-63 J Kerr found pipe after extensive digging. corner lay in center road before regrading - now. lies 1' west of West edge traveled road. - lies 1' South fence running west.
- Dice in power pole. SW 37.35.
drill steel driven just south of fence running west - well above ground W 43.6.
- 16 east set 1/2 x 3' rod. M & L. 1329' see center 2.
- 16 north set 1/2" rod M & L. 1315.9. RoP 1108 1317.3
RP above 1/16 lies 3' east of W edge traveled road.
1/16 lies 27.5' east of N-S fence west road RW.
Dice power pole # 8986 SW 105.5.

#540205 (#2)

Section Corner 2-3-10-11 High Forest 105-14

4-23-76 (1/16W) Dug 4' x 4' x 3' deep. Found post hole or stake hole running down 1'± 3.6 S and 3.7 E of Kastler rod set on line and 1/4 distance. Hole location 1' W of Hunter's measure from 2-3-10-11 and near computed distance S. of straight line between section corner as per Old Survey Book #4 P. 132. Accepted as Hunter 1/16 TL. Set only old fence post in hole as McAdie's will set their corner here. Corner 14' E of N-S fence and 1' S of fence E and in line with row of large trees on E side of fence S.

Govt. M-1-5 Surv by 1853

80.00 Set post for corner to Sec's 2-3-10-11

Bur Oak 8 in N 30 W .72 IKS

Bur Oak 12 in N 57 E 3.61 IKS

11-20-1980 Sec. Cr 2-3-10-11: Took RP's to CIM before road grading. CIM 1½' So. of fence line West and 9' West ℄ N-S road bfore road grading. Set 5/8" rod 88.00 West (1.3 So of fence) and on line to a 5/8" rod 166.95 West of the corner (1.6 So. of fence) The C.H.D. set some tubs East and SE ¼ of the corner.

9/18/89 CIM TOP BROKEN OFF, REF. ROD 88.0' W. MISSING, OTHER TIES GOOD