6-16-1964 set C/M over 3/4 x 12" rod (replace orig) #1
#540305 corner)

section corner 3-4-9-10 Hi Forest 105-14.
6-1876 Hunter P299 no 294 S 3 Mike Shanrahan.
John Linaugh
corner gone established corner by meas.
- meas 1/4 3-4 south to SW cor 10 119.58 making
39.86 as 1/3 distance
- meas SE 3 west to SW 4 159.10 che R 159.90
drove stake properly marked

10-1911 Ch Larson 162B S 3-4-9-10. P Shanrahan.
found small limestone - checking all meas of Hunters
P299 in all directions. as follows.
Corner

Meas north & south 39.86

Meas east very complicated 1876. total length 2 miles
LE 3 to LW 4. 159.10 Record 159.90

Meas east. actual 79.30 or 39.78 to L'4 3 chen 39.52.
Meas west " 79.80 or 40.03 to L'4 4 chen 39.77
L'4 3 stake by cor post. L'4 4 boulder.
- set boulder 12x16x30 as section corner in place limestone.
6-16-1964 J Karr. drill steel riser over stone.
set C I N over 3/4" x 12" rod.

Dice	corner fence post	S.	25.49.
"	tab pole stub	NW	74.2.
"	power pole.	NW	76.3.
Harrow tooth in	burr oak	NE	61.4.

B222 2x14x19 LS - 1" drill steel - Meas West 1895.07 to L'4 5-8
→ Co. Hwy. Dept.

Section Corner 3-4-9-10 High Forest 105-14 #2
#540305

4-23-76 (1/16E) Dug 4'x4'x1' deep to clay at T.H.'s computed location but found nothing.

Coal Notes Yerby 1853

80.00 Set post for corner to Sect 3-4-9-10

Bur Oak 6 N 28 W 108 links

Bur Oak 8 N 36 E 1/8 " "

Bur Oak 6 S 80 E 200 " "

Bur Oak 105 57 W 65 " "

1/14/86 FD CIM BUT SOME SECTIONS BROKEN OFF LEFT AS FD.