6-15-1973 set C I M over 1¼ X 28" ± pipe. #540805 (1)
Cor + 3-13-75
section corner. 7-8-17-18 Hi Forest 105-14.
4-1872 Hunter P194 no 205 by T Donnelson, M Alexon
P Sullivan & others

Found stub of old stake in road,
located by stump of remaining only B tree, checked very closely.
set new stake by its side.

-16 North set stake M & L 19.89.
8" burr oak S 32° E 32½ lks.
12" " " N 82° W 178 "

-16 center S E ¼ set corner by inters lines from
1/16 corners on W & N sides of sections enters 1/16 corners
in S E ¼ ?

over

1/16 west set stake M & L. 20.00.
9" Br Oak N 52° W 26 links 17.16
10" " " N 34° E 72 " 47.52

No Oaks here North

8-1889 Thos Fraser P434 No 421 S8. Rearden.
corner missing, set temp point from line of 1/4 7-8
over 1/16 corner using Hunters mean of 19.89. (1312.74
-16 north found. SE BT of Hunters set new stake
as 1/16 corner- took new B T. ~~N 45½ E~~ N 48 3/4° E 14.52 22 lks 6" Blk Oak.
set stakes for fencing on 1/16 line east. also 1/4 cor east 1/4 7-8.

8-4 to 10-1970 to survey. had to find corner for alignment
of township road. apparent of large kink in road as it runs
west removed entire road with cat after move from north
found road eroded & gone to clear clay (over 3') others had clay.
see card #2.

#540805 (2)

Card # 2 7-8-17-18 H 7 Forest 105-14

section line north had huge kink at ¼ 7-8 see page 194.
- found very likely BT at ⅛ between ¼ 7-8 and SE 7 which placed corner at or very near new corner post (4 way fences)
- found small stone at ¼ 7-8 which checked for mean N & S. and four line set C/M finally at that point, searched for corners on north line L 7 (NE cor C/M) and on ⅛ line E & W of N½ 7 found likely stone (center NW¼ 7 4'± west of new corner post, set stake (limb of tree) in many stones & glass found near stone found no mon.
- mean 1 mile east as well as 1 mile north dug in black top for ¼ 8-17 extensively probed, much old digging done heretofore as at 7-8-17-18 - finally established corner set small pipe at bottom trench dug by cat in wire reel spool ends etc. Made no attempt to set any other corner. - set center stakes each (201)

Meas from corner as follows
North = to 1/16 cor (new proven corner post as corner) 1315.5'
then 1315.5 to CIM set as 1/4 7-8 R 1312.74.
- from CIM at 1/4 7-8 north to CIM as 5-6-7-8 2591.35' R 2591.16
- East = after setting 7-8-17-18 from line & meas from north and unable to find 1/4 8-17. set 1/4 8-17 CIM in black top M & L 2614.53 R 2612.78
RP to corner not set - Nail in hub on SW side 36" brush NW 51.55'
Nail in hub on E side 28" brush - north 97.5' with 3/8" x 3' rod set on transit line to head of rail at 50.0'
- corner about 8.5' east of fence running south. fence north fastened to tree blt on 40' ℄ line from 1/16 north fence has true until last 500

Card # 3 7-8-17-18 High Forest 105-14 (3)
6-15-73. set CIM over 1¼ x 28" pipe. #540805
Complete RPS.

Corner at extreme N edge traveled road surface.
" 8.5' E of fence running south.
51.55' NW To nail (lost gone) in SW side 36" burr oak
97.5 N To nail in hub on E side 28" burr oak.
50.0' N To 3/8 x 36" rod on direct transit line to head of nail in oak (97.5 RP.)
65.5 WNWly To punch hole in top center east end of 24" galv feed drive culvert
the 3/8" rod lies 5.2' E of E edge huge burr oak (6-1973

(over)

Meas elect west (see book & note added later.
Corners Fd by 1953
80.00 set no to set 7-8-17-15
Blk Oak 12. → N. & W 246 lks 162.36
Blk Oak 8. → N 80 E 294 " "

Fall, 1982; Sec. Cor 7-8-17-18: Found CIM and shot. See Drwg
10-29-82, 1/16 North: Dug from a point 1½' East of the 5-17.
t.n., West for 4½' and North for 4' by 3' deep to clay.
We found one small post stub remains 1.8 North and
1.1 West of the t.n. Post dug in but very small
(3" diameter) and only 6" remaining (top down 2½') and
not pointed.

The interior work in Sec. 6 says Hunter corner was at
least 1'N & 6'W of CIM. Measure North says 6' North
from 5'6 & 18 on post @ Cor. 18 says 15½' West, which agrees