1

#541206 (1)

1/4 Corner 11-12. Hi Forest 105-14.
11-1907. Ch Armstrong P110 B dly J Kelly R Thomas & other
set temp point N&L. 39.99. between sec corners 2627.13
LE 11 assumed by rows of trees
NE 11 stone set by measurements.
- west set iron pipe 30" x 1" set N&L. 20.12/1327.9
this pipe came 1½' SW of cor fences N & E.

1966 or 67 J Kerr dug & searched for 1/16 cor. pipe.
for line north may have missed it but not likely.
May have set ½" rod for assumed point for line north
Run line north ½ mile could not find 1/16 pipe west (over

of NE cor 11 which was found & referenced in 1950's.

9-1924. Co H D B43 P2 show Armstrong notes as iron stake.
Meas north 2624.7. - Sta PI at Sec 11-12. 6832.7??
1578.3
5254.4
P110 B shows temp point N&L 2627.13
Stone north - assumed point midway tree rows south at 11-12 & 13-14 where 2 tree rows of cottonwood ran west 10 ft apart.
- Note shows iron west as 1/16 N&L 1334.7. R P110 B 1327.92
Sta at 1-2-11-12 1578.3. Making
5254.4 for mile south. (should try line from west again)

9-8-71 set nail in line of fence west and in center road.
N-S. high grade. this corner in violent boat dispute between Stoltenberg on the north and Neitz farm on the south claim that fence once lay up to 15' north of where it now lay-
cont 2.

Card # 2 1/4 11-12 High Point 105-14. (2)
ran & meas line from CIM over true stone at SW11 east over nail set by Co. HD. accepted as N-S of 1/4 11-14. and rod .95' east of nail on same line accepted as final 1/4 11-14. set nail at 2680.83 from iron at 1/4 11-14 2681.15 E of SW11.
#541206
- ran and meas on random from above nail north over nail set as 1/4 11-12 area. found nail at 2609.48. R 2626.14 cont north to CIM at NE11 line fell 6.2 east of CIM. and total 5247.7. R 5252.28. Midway meas 262385'
- 9-9 ran aerial from CIM at 1/4 10-11 on 45' ⑤ south over 45' ⑤ south at CIM at center 11. Note 1/4 10-11 later found true stone .55 south of CIM point used so ⑤ 44.45' this line intersected east line sec 11 26.88 south of nail or fence line running west. this line would be .55 too far south. or 26.33 of nail over.

this would make nail on line fence west at 2608.93
R. 2626.14. actual midway 2623.85 or 14.92 to for S.
- line at 1/16 west fell at 35.94 north of 45' @ south. or 9.06
too far south. (center corner post).
- corner post of new fence E-W-N came at .1343. east of
C/M. (armstrong pipe below) R. 20.16 1330.56. then 1333.3
east to nail on center road. (direct line would be 3.1' west of nail
or 1330.2. very near record
- dug at 1/16 from fence running north west over 15' to well west
of 1330. and from fence running west over 10' north, could find
no trace of pipe set by armstrong but wire & more wire, set O.
- did find post stub 12.2 east to N-S fence
9.5 South to E W fence.

RP to nail at 1/4 11-12 orig nail 32.5 on transit line over nail
head and center 1/16 corner post W.

1/4 Cor 11-12 High Forest #541206 (3) 105-14

11-19-75 Dug with backhoe at M+L location using post slab found 11-18-75 as Section Corner 11-12-13-14. Dug 6'3'x8' to clay but found nothing. Road cut sharply on East side.

Local RP's to trav. pt: 11.91N ? north.
East Meas Yucky 1053 9.5PE ?
90.00 set 2" steel post in mound of rock and dug-out charcoal, white wash pile planted Osage Orange seeds E+W of rock

9/12/89 FD NAIL WITH HEAD GONE IN CENTER OF N-S RD, INLINE OF FENCE WEST, PROBABLY NAIL SET IN 1971