11-10-1964 set C/M over 1/2 x 24" rod. #541405 ①
section corner 14-15-22-23 Hi Forest 105-14.
6-1899 Pl Fraser P659 No 587 L26 Town boad.
accepted point anered positively by Patrick & Edward Griffin
as to where point corner stood. corner by old
post in east-west fence line under fence.
used to set sec cor. 22-23-26-27.
5-1952 MHD: Found remains of old post; checks close for line & chainage — sly adj. Mon W = 2656.4 found
Minn Hwy Dept Conal
set hub as corner. which came 2651.7 east of
C/M set on highway assumed corner at 1/4 15-22.
MHD found 2"x2" hub Later Note: evident set on post [illegible] W 6.7 E 11.1
11-1964 JKerr accepted corner as found with
above measurements seeming likely correct as possible.
as long as corner stays put. RPs — over

set C I M over 1/2" x 24" rod.

Lath on fence post	E 11.1.
" " " "	W 6.7.
MHD dive in power pole.	W 105.1.
5/8" rod on section line .8' south of power pole.	W 420.0

Cut Notes 4-6-53

80.00 set post to corner for sect 14-15-22-23 in mound of earth & sod deposited charcoal, rock, trench & pits, planted Osage O-range & sod NW & SE

3-22-E4 (1981 Roman BK) Removed steel fence post on North side of CIM under E-W fence and set a survey marker sign and post 1.25 North. This corner 33' West of field fence North.

Minn H. D. (2)

Sec. Cor.
14-15-22-23

N.E. 22 H.E.

Meas. 2650.4 West

M.H.D. ~~Found stake~~

~~with flagging & meas. N.W.~~

5-1958 M.H.D.

Found remains of old post, checks close for line & chainage and is very rotten.

M.H.D. Found 2"x 2" Hub - Later note: ~~Set~~ Replaced

~~by line peg - 27'~~

Se. post 6.71 W.

" " 11.1 E.