1 ~~7-15-71 set 2"x4" pipe by cor post - line & meas from E.~~
6-6-1975 Set C.I.M. over 3/4" x 12" iron in fence line
Section corner 20-21-28-29 Hi Forest 105-14
5-1870 Perry by Hunter P199 no 188 S20 C Wilson
found stake standing J Rogers (1)
- meas north to stake found standing 40.16 #542105
- meas west 39.86 to center "Sluice" Said to be over 1/4 cor. N 1/2° E

6-1892 Thos Fraser P491 no 465 S28 Jon Kelly, Mike Donahue
found stake standing P177.
- east set stake at 4.96 1/2 then set stone boulder at 9.93 3/4 beyond
then 24.84 3/8 boulder set (now CIM) 1629.69
- meas south. 39.92 1/2 to boulder set M & L as corner.

4-1896 T Fraser P594 no 540 S21 P Dillany & others
found corner P 491

over)

-16 east drove iron stake N&L 19.82½ = 1308.45
-16 north set stone 3x4x16 N&L 20.12½
-16 center SW¼ 21 drove iron stake & set stone at witness lines

7-15-71 Co surv. found large bore cedar post. ran and meas. line from C/N over stone at ¼ 21-28, found 1" Fraser iron pipe at 1312.95, found boulder at 1640.13 R 1639.69
large corner post came at 2623.96. R 2623.26
- re set 1/16 with ½" rod at 1312.0 on line & pipe & C/N. 1/16 corner 1' south and 1' east & fence line corner E-W-N.
- set iron by stone at prop corner. east & stone.
- set 5/8" x 5' twisted iron (plate on bottom) at 2296. R 2295.32 Corner came 5.3' west & R.R. rail. corner post. line Center rail
- set 2" x 4' pipe up 18" at corner just NE & by post at 2624.0 - huge pile stones at corner all dug out while searching for stake or corner. no other RPS.

Card # 2 20-21-28-29 High Forest 105-14 (2)

extra records - 1903(?) R Fraser old fieldbook #10 P 19.

Section 29 survey for Egbert Brink (?) #542105

No desc of corner. Meas west "a" to "c" short 34½ links. 22.77 or 5257.23

- 16W "6" for line S to "2" (1/16 between Center 29 and E¼ 29).

remark only " 2 & 6 came east 18¾ links (12.37')

Can't figure what is meaning of that.

Only way to really test corner is to find stone 3X4X16 set by R Fraser N & L 20.12½ (1328.25

6-6-75 Dug around fence post at 1/16 N but found nothing. Fence post fit well with 1/4 Cor 20-21 and Sec. Cor. 20-21-28-29.

6-6-1975 went to Corner location to find pipe set by Corner post (7-15-71) Everything was torn out to put in new fence. Reset Corner by doubling over 1/16 Corner iron east at 1311.93, also ran line over 1/16 post north to 1/4 Cor. 20-21. It fit very well.

set C.I.M. over 3/4" x 12" iron in fence line (East-west)

Gov't Mds Gr. by 1853

40.00 Set post - corner to Sec 20-21-28-29

Bur Oak 3 in N 55 W 42 lks

Bur Oak 10 in N 61 E 117 " "

Bur Oak 4 in S 61 E 177 " "

Bur Oak 12 in S 7 W 521 " "

#542105 (3)

Section Corner 20-21-28-29 High Forest 105-14

Fall, 1982: Found and shot CIM. See DRWG 5-17

10-8-82 E-W fence now gone, only fence ridge remains. Set survey marker sign and post on North side of CIM.