1 8-30-71 set steel fence post as witness from line & meas East
7-23-1974 Set 2 I. M. over 1" Pipe in place of
1/4 corner. 26-27 Hi Forest 105-14 #542606
6-1899 H Fraser P659 no 587 L26 Town Board.
found stake & stone as set by witness tree
the LEBT which checked with govt field notes.
- Meas north 40.04 which was used to set NW26
as 1/3 dist to 14-15 - 22-23.
- Meas east 40.15 2649.9 To stone at Center 26.

12-1910 Ch Larson P146B L27. John Fitzpatrick
Located corner by Witness tree. L 1/16 N 79° E 6.88
1/64 N 3½° E "
. Meas west to ℄ railroad right of way 298'
1/64 cor north line 180' east of ℄ railroad right of way.

8-19-71 set random nail on projected line using nail set at center 26 by Co H & D RPs. and center road east. Nail came on N edge low, overflow river road. at 2659.13 R2649.9

8-27-71 re run line only after finding center 26. and 1/4 25-26. Carefully, line came on extreme south edge road.

8-30-71 dug entire S 1/2 of road well into black clean soil below rock road fill found no stone or stake pro-rated meas as on east half. and set green full length steel fence post driven 4" below top of road on final line at. 2648.05 R2649.9

9-10-71 meas north of steel post found undisputed L stone in open pasture set by Ch Armstrong as 1/64 corner. (No meas). at 666.9 no meas given. Center road would be close to 660' ±??

see card # 2.

Card #2. 1/4 26-27. High Forest 105-14 #542606 (2)
road could be dug to center road as graded but line as
now run hits center bridge O.K. - Corner post left as is.
RPS to steel post corner 1/4 26-27.
10.66 4' W of L to Dr Pepper cap E side corner post of short
fence running SW ly. (line of fence in line corner as set).
61.62 SE to pepsi cap on SW side PP # 44222.
88.5 NNW to large 28" ash center (southerly of twin trees)
151.8 NNE to center 36" ash (leaning south considerably)
birch trees scarred badly by flood ice.
Corner lies about 153 ± ~~West~~ S. west edge concrete
floor of bridge. and at edge of grass on S edge road.
(over.

Note. if Chas Armstrong (Larson) used true stone at 1/4 26-27 and corner as set at 22-23-26-27, and line from corner as set at 1/4 26-27 over stone found at 666.9 fell 6.4 W of Corner as set at 22-23-26-27. then 1/4 26-27 would have to move W about 2.1' to line up 666.9 stone and 2642.7 pipe set

---

July 23, 1974 — Set C.I.M. over 1" pipe
Set in place of steel fe post, removed post.
Note: This Corner could have moved ± 0.66' West
To be in Same proportion as E. 1/4 line after
Measuring by Electronic; however, Corner has been
used To Subdivide Section 27 To West by Mcchied Bells
So we decided To leave Corner as established in 1971

#542606 | 3

High fence 1/4 corner 26-27
Gov't Mons 4" by 4" 1553
40.00 set a 1/4 steel post
Ash 8" in N28 W82 1/5
Elm 10" in S69 E294 1/5

3/28/97 GGG reports 1/2" iron at corner

7-22-97 FOUND 1/2" REBAR OVER CIM. TOP OF CIM 26" DEEP ON DITCH SLOPE ON SOUTH SIDE CR #120. SET 1" SR PIPE/CAP OVER CIM. THE CORNER FALLS 12' SOUTH OF ℄ CR #120 + 5½' EAST OF STUB FENCE SOUTH.