1 11-18-75 Set CIM #542805

section corner. 28-29-32-33 Hi Forest 10 5-14.
6-1892 (2 bos Grassy P491 Bk 965 L28 Jm Kelly Mike Donahue.
W. M. C. Fraser = Deputy
Could find no trace of corner - replaced by meas.
- Meas - NW cor 28 to SW cor 33 39.92 1/2 (2635.05 4 times.
where found stone set by Hunter (SW 33) - nothing between short 31 1/2 L.
- meas from S 1/4 28 west to SW cor 29. found stone set by Hunter
fell short gave meas. 4 links or 1/3 chs per half mile.
plat calls for 39.93 2/3 = 2635.82 from above sec cor east to S 1/4 28
(but likely ~~meant to place 39.98 2/3 - 4 thereat plain~~ (Gov't Meas Sec. 29 = 804
~~Typical 2 bos Fraser - either not down at all or wrong~~)

10-1904 Ch Armstrong P94B L33 McCall & Stewart.
found boulder P49

over

- meas east 2634.25' To corner affixed M & L on face of bridge abutment see N 1/4 33

Probably incorrect info

- meas south 2634.75 to temp point in gen field.

Co H.D. B321 1966 - used corner set by M H Dept.
Meas west 2655.42 ~~R2634.12. P.491~~ P388 R 5206.4 - 2653.2
Meas east 2634.25 R 2634.25 94B P491 R. 2699.12
3/8" rod over spike 60D — Sp D cor FP SE 82.65
Sp D cor P N 35.37 - Sp D PP SSW 52.03

M. H. D. - 1958

used E Gravel Road & in line fence - North (M.H.D. - 9-24-58
dug down 3' to 4' found Nothing Sp. 5580-02
T.H.90-391
Dm. Co. line To This
2653.2' East

Set iron rod

1903 R Fraser old fieldbook #10 P19 "H to F" over run 35 1/4 lks (23.26'
or 2663.26' "H to E" corrected but not "H to F" No dogs

542805 | 2

Section Corner 28-29-32-33 High Forest 105-14

11-18-75 Dug along side 3/4" rod found 5-75. Found huge boulder with cross on top and packed in small boulders 3½' deep. Put junk around stone. Set CIM over 3/4" x 10" rod over stone. Corner 3½' W of fence North and just on the N side of ℄ E-W road (Co. Rd 35). ~~3½' W of fence North~~ Rod found 5-75 was 2.75' W and .8' N of traverse nail and stone bin .46' W and .10' N of rod (pulled).

R.P.'s: CSD in telephone pole NW 134.96
CSD N side corner post NNE 51.66
CSD E side pp # 10873 SSW 51.99

Punch hole top W end 18" CMP to field drive south SE 67.37

CSD N side of E gate post to field drive South SE 92.83

CSD S. side telephone pole NE 141.78

Cor Notes Set by 1853

80.00 Set-post-cor to stake 28-29-32-33

Bur Oak 10 in Dist E 27c lks

Bur Oak 14 in S 10 W 19 lks

Made tie

10-26-94 FD CIM IN GOOD SHAPE IN BLACK TOP CR #35

SECTION CORNER 28-29-32-33 HIGH FOREST 105-14 (3)
#542805

7-1-96 FOUND CIM IN GOOD CONDITION. SET REF PIPE W/CAP ON WEST EDGE FIELD DRIVE IN NW 1/4 SEC 33.
℄ CR #35 NORTH 29 1/2'. ℄ FIELD DRIVE EAST 11'.
T@ REF PIPE
4RT P.K. NAIL IN PP # 10874 (1ST POLE EAST OF COR) TO SEC COR
201° 30' 40"
TO SEC COR 28-29-32-33 HOR 64.91

7-8-96 REMOVED CIM
10-25-96 CHD SET 1" SA PIPE W/CAP